

Photos – The Enniskillen Lodge



Enniskillen Lodge, 2003




Enniskillen Lodge, 2022



Request to remove panel door (left) and replace with window of the same size and shape of existing windows (six-over-six with mullion bars, including window sill). Brickwork and pointing below new window to be in keeping with existing, e.g. colour, size, material, pattern.



Broken window glass to be repaired; windows being replaced to match original shape and design (six-over-six with mullion bars).



Request to remove entry door and replace with window of same size and shape of existing (six-over-six with mullion bars, including window sill). Brickwork and pointing below new window to be in keeping with existing, e.g. colour, size, material, pattern.



Repointing masonry joints as and where required; should be in based upon the original mortar mix and completed in the original pointing style, either beaded or tuck pointing. Restore or replace loose, cracked, deteriorating or missing brickwork using similar clay brick (size and colour).