

Project Name: Lindsay Maintenance

| | | | | | |
|---------------------------|--------------------------------|--------------------------------|--------------------------------------|--|-----------------------|
| Final Project Cost | Additional County Costs | Total Report Assessment | Total Agricultural Assessment | Pro Rated Agricultural Assessment | Grant Received |
| \$7,408.13 | | \$2,176.00 | \$1,101.66 | \$3,750.56 | \$1,134.20 |

| Roll Number | Total Assessment | Agricultural Lands Assessed (\$) | Gross Costs (\$) | Agricultural Lands Assessed (\$) | Non Agricultural Lands Assessed (\$) | Grant Received (\$) | Net Assessment (\$) |
|--------------------|------------------|----------------------------------|------------------|----------------------------------|--------------------------------------|---------------------|---------------------|
| 023-006-06600-0000 | 45.00 | \$ 45.00 | \$ 153.20 | \$ 153.20 | \$ - | \$ 46.33 | \$ 106.87 |
| 023-006-07000-0000 | 15.00 | \$ 15.00 | \$ 51.07 | \$ 51.07 | \$ - | \$ 15.44 | \$ 35.63 |
| 023-006-07100-0000 | 15.00 | \$ 15.00 | \$ 51.07 | \$ 51.07 | \$ - | \$ 15.44 | \$ 35.63 |
| 023-006-07300-0000 | 15.00 | \$ 15.00 | \$ 51.07 | \$ 51.07 | \$ - | \$ 15.44 | \$ 35.63 |
| 023-006-07400-0000 | 10.00 | \$ 10.00 | \$ 34.04 | \$ 34.04 | \$ - | \$ 10.29 | \$ 23.75 |
| 023-006-07500-0000 | 25.00 | \$ 25.00 | \$ 85.11 | \$ 85.11 | \$ - | \$ 25.74 | \$ 59.37 |
| 023-006-07600-0000 | 6.00 | \$ 6.00 | \$ 20.43 | \$ 20.43 | \$ - | \$ 6.18 | \$ 14.25 |
| 023-006-07700-0000 | 45.00 | \$ 45.00 | \$ 153.20 | \$ 153.20 | \$ - | \$ 46.33 | \$ 106.87 |
| 025-001-04200-0000 | 25.00 | \$ - | \$ 85.11 | \$ - | \$ 85.11 | \$ - | \$ 85.11 |
| 025-001-04500-0000 | 16.00 | \$ 16.00 | \$ 54.47 | \$ 54.47 | \$ - | \$ 16.47 | \$ 38.00 |
| 025-001-10900-0000 | 0.50 | \$ - | \$ 1.70 | \$ - | \$ 1.70 | \$ - | \$ 1.70 |
| 025-001-12000-0000 | 0.50 | \$ - | \$ 1.70 | \$ - | \$ 1.70 | \$ - | \$ 1.70 |
| 025-001-12100-0000 | 1.00 | \$ - | \$ 3.40 | \$ - | \$ 3.40 | \$ - | \$ 3.40 |
| 025-001-12200-0000 | 0.50 | \$ - | \$ 1.70 | \$ - | \$ 1.70 | \$ - | \$ 1.70 |
| 025-001-12600-0000 | 1.50 | \$ - | \$ 5.11 | \$ - | \$ 5.11 | \$ - | \$ 5.11 |
| 025-001-12900-0000 | 0.50 | \$ - | \$ 1.70 | \$ - | \$ 1.70 | \$ - | \$ 1.70 |
| 025-001-13000-0000 | 0.50 | \$ - | \$ 1.70 | \$ - | \$ 1.70 | \$ - | \$ 1.70 |
| 025-001-13100-0000 | 0.50 | \$ - | \$ 1.70 | \$ - | \$ 1.70 | \$ - | \$ 1.70 |
| 025-001-13200-0000 | 0.50 | \$ - | \$ 1.70 | \$ - | \$ 1.70 | \$ - | \$ 1.70 |
| 025-001-13300-0000 | 0.50 | \$ - | \$ 1.70 | \$ - | \$ 1.70 | \$ - | \$ 1.70 |
| 025-001-13500-0000 | 0.50 | \$ - | \$ 1.70 | \$ - | \$ 1.70 | \$ - | \$ 1.70 |
| 025-001-13600-0000 | 0.50 | \$ - | \$ 1.70 | \$ - | \$ 1.70 | \$ - | \$ 1.70 |
| 025-001-13900-0000 | 0.50 | \$ - | \$ 1.70 | \$ - | \$ 1.70 | \$ - | \$ 1.70 |
| 025-001-14000-0000 | 0.50 | \$ - | \$ 1.70 | \$ - | \$ 1.70 | \$ - | \$ 1.70 |
| 025-001-14100-0000 | 0.50 | \$ - | \$ 1.70 | \$ - | \$ 1.70 | \$ - | \$ 1.70 |
| 025-001-14300-0000 | 0.50 | \$ - | \$ 1.70 | \$ - | \$ 1.70 | \$ - | \$ 1.70 |
| 025-001-14400-0000 | 0.50 | \$ - | \$ 1.70 | \$ - | \$ 1.70 | \$ - | \$ 1.70 |
| 025-001-14500-0000 | 0.50 | \$ - | \$ 1.70 | \$ - | \$ 1.70 | \$ - | \$ 1.70 |
| 025-001-14700-0000 | 0.50 | \$ - | \$ 1.70 | \$ - | \$ 1.70 | \$ - | \$ 1.70 |
| 025-001-14800-0000 | 0.50 | \$ - | \$ 1.70 | \$ - | \$ 1.70 | \$ - | \$ 1.70 |
| 025-001-15000-0000 | 2.00 | \$ - | \$ 6.81 | \$ - | \$ 6.81 | \$ - | \$ 6.81 |
| 025-001-15100-0000 | 2.00 | \$ - | \$ 6.81 | \$ - | \$ 6.81 | \$ - | \$ 6.81 |
| 025-001-15200-0000 | 2.00 | \$ - | \$ 6.81 | \$ - | \$ 6.81 | \$ - | \$ 6.81 |
| 025-001-15300-0000 | 2.00 | \$ - | \$ 6.81 | \$ - | \$ 6.81 | \$ - | \$ 6.81 |
| 025-001-15400-0000 | 184.64 | \$ - | \$ 628.60 | \$ - | \$ 628.60 | \$ - | \$ 628.60 |
| 025-001-15500-0000 | 2.00 | \$ - | \$ 6.81 | \$ - | \$ 6.81 | \$ - | \$ 6.81 |
| 025-001-15600-0000 | 2.00 | \$ - | \$ 6.81 | \$ - | \$ 6.81 | \$ - | \$ 6.81 |
| 025-001-15800-0000 | 2.00 | \$ - | \$ 6.81 | \$ - | \$ 6.81 | \$ - | \$ 6.81 |
| 025-001-15810-0000 | 2.00 | \$ - | \$ 6.81 | \$ - | \$ 6.81 | \$ - | \$ 6.81 |
| 025-001-16200-0000 | 22.00 | \$ 22.00 | \$ 74.90 | \$ 74.90 | \$ - | \$ 22.65 | \$ 52.25 |
| 025-001-16220-0000 | 0.50 | \$ - | \$ 1.70 | \$ - | \$ 1.70 | \$ - | \$ 1.70 |
| 025-001-16240-0000 | 0.50 | \$ - | \$ 1.70 | \$ - | \$ 1.70 | \$ - | \$ 1.70 |
| 025-001-16300-0000 | 2.00 | \$ - | \$ 6.81 | \$ - | \$ 6.81 | \$ - | \$ 6.81 |
| 025-001-16400-0000 | 2.00 | \$ - | \$ 6.81 | \$ - | \$ 6.81 | \$ - | \$ 6.81 |
| 025-001-16500-0000 | 2.00 | \$ - | \$ 6.81 | \$ - | \$ 6.81 | \$ - | \$ 6.81 |
| 025-001-16700-0000 | 2.00 | \$ - | \$ 6.81 | \$ - | \$ 6.81 | \$ - | \$ 6.81 |
| 025-001-16800-0000 | 2.00 | \$ - | \$ 6.81 | \$ - | \$ 6.81 | \$ - | \$ 6.81 |
| 025-001-16900-0000 | 2.00 | \$ - | \$ 6.81 | \$ - | \$ 6.81 | \$ - | \$ 6.81 |
| 025-001-17000-0000 | 2.00 | \$ - | \$ 6.81 | \$ - | \$ 6.81 | \$ - | \$ 6.81 |
| 025-001-17100-0000 | 2.00 | \$ - | \$ 6.81 | \$ - | \$ 6.81 | \$ - | \$ 6.81 |
| 025-001-17200-0000 | 2.00 | \$ - | \$ 6.81 | \$ - | \$ 6.81 | \$ - | \$ 6.81 |
| 025-001-17400-0000 | 2.00 | \$ - | \$ 6.81 | \$ - | \$ 6.81 | \$ - | \$ 6.81 |
| 025-001-17500-0000 | 2.00 | \$ - | \$ 6.81 | \$ - | \$ 6.81 | \$ - | \$ 6.81 |
| 025-001-17550-0000 | 2.00 | \$ - | \$ 6.81 | \$ - | \$ 6.81 | \$ - | \$ 6.81 |
| 025-001-17600-0000 | 2.00 | \$ - | \$ 6.81 | \$ - | \$ 6.81 | \$ - | \$ 6.81 |
| 025-001-17700-0000 | 2.00 | \$ - | \$ 6.81 | \$ - | \$ 6.81 | \$ - | \$ 6.81 |
| 025-001-17800-0000 | 2.00 | \$ - | \$ 6.81 | \$ - | \$ 6.81 | \$ - | \$ 6.81 |
| 025-001-17900-0000 | 2.00 | \$ - | \$ 6.81 | \$ - | \$ 6.81 | \$ - | \$ 6.81 |
| 025-001-18100-0000 | 2.00 | \$ - | \$ 6.81 | \$ - | \$ 6.81 | \$ - | \$ 6.81 |
| 025-001-18200-0000 | 2.00 | \$ - | \$ 6.81 | \$ - | \$ 6.81 | \$ - | \$ 6.81 |
| 025-001-18400-0000 | 2.00 | \$ - | \$ 6.81 | \$ - | \$ 6.81 | \$ - | \$ 6.81 |
| 025-001-18500-0000 | 2.00 | \$ - | \$ 6.81 | \$ - | \$ 6.81 | \$ - | \$ 6.81 |

| | | | | | | | | | | | | | |
|--------------------|--------|----|--------|----|--------|----|--------|----|-------|----|--------|----|--------|
| 025-001-18600-0000 | 2.00 | \$ | - | \$ | 6.81 | \$ | - | \$ | 6.81 | \$ | - | \$ | 6.81 |
| 025-001-18700-0000 | 0.50 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 |
| 025-001-18704-0000 | 0.31 | \$ | - | \$ | 1.06 | \$ | - | \$ | 1.06 | \$ | - | \$ | 1.06 |
| 025-001-18705-0000 | 0.31 | \$ | - | \$ | 1.06 | \$ | - | \$ | 1.06 | \$ | - | \$ | 1.06 |
| 025-001-18706-0000 | 0.31 | \$ | - | \$ | 1.06 | \$ | - | \$ | 1.06 | \$ | - | \$ | 1.06 |
| 025-001-18707-0000 | 0.31 | \$ | - | \$ | 1.06 | \$ | - | \$ | 1.06 | \$ | - | \$ | 1.06 |
| 025-001-18708-0000 | 0.31 | \$ | - | \$ | 1.06 | \$ | - | \$ | 1.06 | \$ | - | \$ | 1.06 |
| 025-001-18709-0000 | 0.31 | \$ | - | \$ | 1.06 | \$ | - | \$ | 1.06 | \$ | - | \$ | 1.06 |
| 025-001-18710-0000 | 0.31 | \$ | - | \$ | 1.06 | \$ | - | \$ | 1.06 | \$ | - | \$ | 1.06 |
| 025-001-18711-0000 | 0.31 | \$ | - | \$ | 1.06 | \$ | - | \$ | 1.06 | \$ | - | \$ | 1.06 |
| 025-001-18712-0000 | 0.31 | \$ | - | \$ | 1.06 | \$ | - | \$ | 1.06 | \$ | - | \$ | 1.06 |
| 025-001-18714-0000 | 0.31 | \$ | - | \$ | 1.06 | \$ | - | \$ | 1.06 | \$ | - | \$ | 1.06 |
| 025-001-18715-0000 | 0.31 | \$ | - | \$ | 1.06 | \$ | - | \$ | 1.06 | \$ | - | \$ | 1.06 |
| 025-001-18716-0000 | 0.31 | \$ | - | \$ | 1.06 | \$ | - | \$ | 1.06 | \$ | - | \$ | 1.06 |
| 025-001-18750-0000 | 0.31 | \$ | - | \$ | 1.06 | \$ | - | \$ | 1.06 | \$ | - | \$ | 1.06 |
| 025-001-18760-0000 | 0.31 | \$ | - | \$ | 1.06 | \$ | - | \$ | 1.06 | \$ | - | \$ | 1.06 |
| 025-001-18770-0000 | 0.31 | \$ | - | \$ | 1.06 | \$ | - | \$ | 1.06 | \$ | - | \$ | 1.06 |
| 025-001-18780-0000 | 0.31 | \$ | - | \$ | 1.06 | \$ | - | \$ | 1.06 | \$ | - | \$ | 1.06 |
| 025-001-18790-0000 | 0.31 | \$ | - | \$ | 1.06 | \$ | - | \$ | 1.06 | \$ | - | \$ | 1.06 |
| 025-001-18800-0000 | 1.75 | \$ | - | \$ | 5.96 | \$ | - | \$ | 5.96 | \$ | - | \$ | 5.96 |
| 025-001-18900-0000 | 1.75 | \$ | - | \$ | 5.96 | \$ | - | \$ | 5.96 | \$ | - | \$ | 5.96 |
| 025-001-19000-0000 | 1.75 | \$ | - | \$ | 5.96 | \$ | - | \$ | 5.96 | \$ | - | \$ | 5.96 |
| 025-001-19200-0000 | 1.75 | \$ | - | \$ | 5.96 | \$ | - | \$ | 5.96 | \$ | - | \$ | 5.96 |
| 025-001-19400-0000 | 1.75 | \$ | - | \$ | 5.96 | \$ | - | \$ | 5.96 | \$ | - | \$ | 5.96 |
| 025-001-19500-0000 | 1.75 | \$ | - | \$ | 5.96 | \$ | - | \$ | 5.96 | \$ | - | \$ | 5.96 |
| 025-001-19700-0000 | 1.75 | \$ | - | \$ | 5.96 | \$ | - | \$ | 5.96 | \$ | - | \$ | 5.96 |
| 025-001-19800-0000 | 1.75 | \$ | - | \$ | 5.96 | \$ | - | \$ | 5.96 | \$ | - | \$ | 5.96 |
| 025-001-19900-0000 | 1.75 | \$ | - | \$ | 5.96 | \$ | - | \$ | 5.96 | \$ | - | \$ | 5.96 |
| 025-001-20000-0000 | 1.75 | \$ | - | \$ | 5.96 | \$ | - | \$ | 5.96 | \$ | - | \$ | 5.96 |
| 025-001-20200-0000 | 1.75 | \$ | - | \$ | 5.96 | \$ | - | \$ | 5.96 | \$ | - | \$ | 5.96 |
| 025-001-20300-0000 | 1.75 | \$ | - | \$ | 5.96 | \$ | - | \$ | 5.96 | \$ | - | \$ | 5.96 |
| 025-001-20400-0000 | 1.75 | \$ | - | \$ | 5.96 | \$ | - | \$ | 5.96 | \$ | - | \$ | 5.96 |
| 025-001-20500-0000 | 1.75 | \$ | - | \$ | 5.96 | \$ | - | \$ | 5.96 | \$ | - | \$ | 5.96 |
| 025-001-20600-0000 | 1.75 | \$ | - | \$ | 5.96 | \$ | - | \$ | 5.96 | \$ | - | \$ | 5.96 |
| 025-001-20900-0000 | 1.75 | \$ | - | \$ | 5.96 | \$ | - | \$ | 5.96 | \$ | - | \$ | 5.96 |
| 025-001-21000-0000 | 1.75 | \$ | - | \$ | 5.96 | \$ | - | \$ | 5.96 | \$ | - | \$ | 5.96 |
| 025-001-21100-0000 | 1.75 | \$ | - | \$ | 5.96 | \$ | - | \$ | 5.96 | \$ | - | \$ | 5.96 |
| 025-001-21200-0000 | 1.75 | \$ | - | \$ | 5.96 | \$ | - | \$ | 5.96 | \$ | - | \$ | 5.96 |
| 025-001-21300-0000 | 1.75 | \$ | - | \$ | 5.96 | \$ | - | \$ | 5.96 | \$ | - | \$ | 5.96 |
| 025-001-21500-0000 | 1.00 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 |
| 025-001-21600-0000 | 1.00 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 |
| 025-001-21610-0000 | 1.00 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 |
| 025-001-21700-0000 | 1.00 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 |
| 025-001-21800-0000 | 1.00 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 |
| 025-001-21900-0000 | 1.00 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 |
| 025-001-22000-0000 | 1.00 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 |
| 025-001-22100-0000 | 1.00 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 |
| 025-001-22200-0000 | 1.00 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 |
| 025-001-22300-0000 | 1.00 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 |
| 025-001-22310-0000 | 3.56 | \$ | - | \$ | 12.12 | \$ | - | \$ | 12.12 | \$ | - | \$ | 12.12 |
| 025-001-22312-0000 | 3.44 | \$ | - | \$ | 11.71 | \$ | - | \$ | 11.71 | \$ | - | \$ | 11.71 |
| 025-001-22400-0000 | 1.00 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 |
| 025-001-22500-0000 | 1.00 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 |
| 025-001-22600-0000 | 1.00 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 |
| 025-001-22700-0000 | 1.00 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 |
| 025-001-22800-0000 | 1.00 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 |
| 025-001-22900-0000 | 5.00 | \$ | - | \$ | 17.02 | \$ | - | \$ | 17.02 | \$ | - | \$ | 17.02 |
| 025-001-31100-0000 | 25.00 | \$ | - | \$ | 85.11 | \$ | - | \$ | 85.11 | \$ | - | \$ | 85.11 |
| 025-001-31600-0000 | 290.00 | \$ | 290.00 | \$ | 987.30 | \$ | 987.30 | \$ | - | \$ | 298.57 | \$ | 688.73 |
| 025-001-31800-0000 | 1.00 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 |
| 025-001-32000-0000 | 90.00 | \$ | 90.00 | \$ | 306.40 | \$ | 306.40 | \$ | - | \$ | 92.66 | \$ | 213.74 |
| 025-001-32100-0000 | 17.00 | \$ | - | \$ | 57.88 | \$ | - | \$ | 57.88 | \$ | - | \$ | 57.88 |
| 025-001-32110-0000 | 3.00 | \$ | 3.00 | \$ | 10.21 | \$ | 10.21 | \$ | - | \$ | 3.09 | \$ | 7.12 |
| 025-001-32150-0000 | 35.00 | \$ | 35.00 | \$ | 119.16 | \$ | 119.16 | \$ | - | \$ | 36.03 | \$ | 83.13 |
| 025-001-32200-0000 | 40.00 | \$ | 40.00 | \$ | 136.18 | \$ | 136.18 | \$ | - | \$ | 41.18 | \$ | 95.00 |
| 025-001-33600-0000 | 3.00 | \$ | - | \$ | 10.21 | \$ | - | \$ | 10.21 | \$ | - | \$ | 10.21 |
| 025-001-33700-0000 | 0.50 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 |
| 025-001-33800-0000 | 3.00 | \$ | - | \$ | 10.21 | \$ | - | \$ | 10.21 | \$ | - | \$ | 10.21 |
| 025-001-33850-0000 | 3.00 | \$ | - | \$ | 10.21 | \$ | - | \$ | 10.21 | \$ | - | \$ | 10.21 |
| 025-001-33900-0000 | 3.00 | \$ | - | \$ | 10.21 | \$ | - | \$ | 10.21 | \$ | - | \$ | 10.21 |
| 025-001-34000-0000 | 1.00 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 |
| 025-001-34100-0000 | 1.00 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 |

| | | | | | | | | | | | | | |
|--------------------|--------|----|-------|----|--------|----|--------|----|--------|----|-------|----|--------|
| 025-001-34200-0000 | 1.00 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 |
| 025-001-34300-0000 | 1.00 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 |
| 025-001-34400-0000 | 1.00 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 |
| 025-001-34500-0000 | 105.00 | \$ | - | \$ | 357.47 | \$ | - | \$ | 357.47 | \$ | - | \$ | 357.47 |
| 025-001-34600-0000 | 2.00 | \$ | - | \$ | 6.81 | \$ | - | \$ | 6.81 | \$ | - | \$ | 6.81 |
| 025-001-34700-0000 | 70.00 | \$ | 70.00 | \$ | 238.31 | \$ | 238.31 | \$ | - | \$ | 72.07 | \$ | 166.24 |
| 025-001-34750-0000 | 15.00 | \$ | - | \$ | 51.07 | \$ | - | \$ | 51.07 | \$ | - | \$ | 51.07 |
| 025-001-34760-0000 | 15.00 | \$ | 15.00 | \$ | 51.07 | \$ | 51.07 | \$ | - | \$ | 15.44 | \$ | 35.63 |
| 025-001-34800-0000 | 1.00 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 |
| 025-001-36100-0000 | 31.00 | \$ | - | \$ | 105.54 | \$ | - | \$ | 105.54 | \$ | - | \$ | 105.54 |
| 025-001-36200-0000 | 1.00 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 |
| 025-001-36300-0000 | 1.00 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 |
| 025-001-36400-0000 | 0.50 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 |
| 025-001-36450-0000 | 0.50 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 |
| 025-001-36500-0000 | 63.00 | \$ | 63.00 | \$ | 214.48 | \$ | 214.48 | \$ | - | \$ | 64.86 | \$ | 149.62 |
| 025-001-36503-0000 | 2.31 | \$ | 2.31 | \$ | 7.86 | \$ | 7.86 | \$ | - | \$ | 2.38 | \$ | 5.48 |
| 025-001-36504-0000 | 1.52 | \$ | 1.52 | \$ | 5.17 | \$ | 5.17 | \$ | - | \$ | 1.56 | \$ | 3.61 |
| 025-001-36505-0000 | 1.63 | \$ | 1.63 | \$ | 5.55 | \$ | 5.55 | \$ | - | \$ | 1.68 | \$ | 3.87 |
| 025-001-36550-0000 | 1.00 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 |
| 025-001-36600-0000 | 1.00 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 |
| 025-001-36700-0000 | 4.00 | \$ | - | \$ | 13.62 | \$ | - | \$ | 13.62 | \$ | - | \$ | 13.62 |
| 025-001-36800-0000 | 0.50 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 |
| 025-001-36810-0000 | 0.50 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 |
| 025-001-36812-0000 | 0.83 | \$ | - | \$ | 2.83 | \$ | - | \$ | 2.83 | \$ | - | \$ | 2.83 |
| 025-001-36813-0000 | 0.80 | \$ | - | \$ | 2.72 | \$ | - | \$ | 2.72 | \$ | - | \$ | 2.72 |
| 025-001-36900-0000 | 0.50 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 |
| 025-001-37000-0000 | 0.50 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 |
| 025-001-37050-0000 | 0.50 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 |
| 025-001-37700-0000 | 2.00 | \$ | - | \$ | 6.81 | \$ | - | \$ | 6.81 | \$ | - | \$ | 6.81 |
| 025-001-37800-0000 | 2.00 | \$ | - | \$ | 6.81 | \$ | - | \$ | 6.81 | \$ | - | \$ | 6.81 |
| 025-001-37900-0000 | 2.00 | \$ | - | \$ | 6.81 | \$ | - | \$ | 6.81 | \$ | - | \$ | 6.81 |
| 025-001-37950-0000 | 2.00 | \$ | - | \$ | 6.81 | \$ | - | \$ | 6.81 | \$ | - | \$ | 6.81 |
| 025-001-37955-0000 | 1.00 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 |
| 025-001-38000-0000 | 2.00 | \$ | - | \$ | 6.81 | \$ | - | \$ | 6.81 | \$ | - | \$ | 6.81 |
| 025-001-38100-0000 | 1.00 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 |
| 025-001-38200-0000 | 1.00 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 |
| 025-001-38300-0000 | 2.00 | \$ | - | \$ | 6.81 | \$ | - | \$ | 6.81 | \$ | - | \$ | 6.81 |
| 025-001-38400-0000 | 2.00 | \$ | - | \$ | 6.81 | \$ | - | \$ | 6.81 | \$ | - | \$ | 6.81 |
| 025-001-38500-0000 | 2.00 | \$ | - | \$ | 6.81 | \$ | - | \$ | 6.81 | \$ | - | \$ | 6.81 |
| 025-001-38600-0000 | 2.00 | \$ | - | \$ | 6.81 | \$ | - | \$ | 6.81 | \$ | - | \$ | 6.81 |
| 025-001-38700-0000 | 2.00 | \$ | - | \$ | 6.81 | \$ | - | \$ | 6.81 | \$ | - | \$ | 6.81 |
| 025-001-38800-0000 | 2.00 | \$ | - | \$ | 6.81 | \$ | - | \$ | 6.81 | \$ | - | \$ | 6.81 |
| 025-001-38900-0000 | 2.00 | \$ | - | \$ | 6.81 | \$ | - | \$ | 6.81 | \$ | - | \$ | 6.81 |
| 025-001-39000-0000 | 0.50 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 |
| 025-001-39900-0000 | 0.50 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 |
| 025-001-39901-0000 | 0.50 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 |
| 025-001-40100-0000 | 1.00 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 |
| 025-001-40300-0000 | 1.00 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 |
| 025-001-40500-0000 | 0.50 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 |
| 025-001-40600-0000 | 0.50 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 |
| 025-001-40700-0000 | 0.50 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 |
| 025-001-40800-0000 | 0.50 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 |
| 025-001-40900-0000 | 0.50 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 |
| 025-002-00100-0000 | 1.00 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 |
| 025-002-00105-0000 | 1.00 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 |
| 025-002-00110-0000 | 0.50 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 |
| 025-002-00120-0000 | 0.50 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 |
| 025-002-00125-0000 | 0.50 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 |
| 025-002-00200-0000 | 1.00 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 |
| 025-002-00210-0000 | 0.50 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 |
| 025-002-00220-0000 | 0.50 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 |
| 025-002-00300-0000 | 6.00 | \$ | - | \$ | 20.43 | \$ | - | \$ | 20.43 | \$ | - | \$ | 20.43 |
| 025-002-00305-0000 | 0.50 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 |
| 025-002-00310-0000 | 0.50 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 |
| 025-002-00315-0000 | 0.50 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 |
| 025-002-00320-0000 | 0.50 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 |
| 025-002-00325-0000 | 0.50 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 |
| 025-002-00330-0000 | 0.50 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 |
| 025-002-00335-0000 | 0.50 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 |
| 025-002-00340-0000 | 0.50 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 |
| 025-002-00345-0000 | 0.50 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 |
| 025-002-00350-0000 | 0.50 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 |

| | | | | | | | | | | | | | |
|--------------------|--------------------|-----------|-----------------|-----------|-----------------|-----------|-----------------|-----------|-----------------|-----------------------------|-----------------|-----------|--------------------|
| 025-002-00355-0000 | 0.50 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 |
| 025-002-00360-0000 | 0.50 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 |
| 025-002-00365-0000 | 0.50 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 |
| 025-002-00370-0000 | 0.50 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 |
| 025-002-00375-0000 | 0.50 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 |
| 025-002-00380-0000 | 0.50 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 |
| 025-002-00385-0000 | 0.50 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 |
| 025-002-00390-0000 | 0.50 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 |
| 025-002-00395-0000 | 0.50 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 |
| 025-002-00400-0000 | 1.00 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 |
| 025-002-00410-0000 | 0.50 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 |
| 025-002-00415-0000 | 0.50 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 |
| 025-002-00420-0000 | 0.50 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 |
| 025-002-00425-0000 | 0.50 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 |
| 025-002-00435-0000 | 2.00 | \$ | - | \$ | 6.81 | \$ | - | \$ | 6.81 | \$ | - | \$ | 6.81 |
| 025-002-00440-0000 | 0.50 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 |
| 025-002-00445-0000 | 0.50 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 |
| 025-002-00450-0000 | 0.50 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 |
| 025-002-00455-0000 | 0.50 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 |
| 025-002-00460-0000 | 0.50 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 |
| 025-002-00465-0000 | 0.50 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 | \$ | - | \$ | 1.70 |
| 025-002-00500-0000 | 6.45 | \$ | - | \$ | 21.96 | \$ | - | \$ | 21.96 | \$ | - | \$ | 21.96 |
| 025-002-00510-0000 | 6.70 | \$ | - | \$ | 22.81 | \$ | - | \$ | 22.81 | \$ | - | \$ | 22.81 |
| 025-002-00520-0000 | 6.85 | \$ | - | \$ | 23.32 | \$ | - | \$ | 23.32 | \$ | - | \$ | 23.32 |
| 025-002-00600-0000 | 17.00 | \$ | - | \$ | 57.88 | \$ | - | \$ | 57.88 | \$ | - | \$ | 57.88 |
| 025-002-00610-0000 | 2.00 | \$ | - | \$ | 6.81 | \$ | - | \$ | 6.81 | \$ | - | \$ | 6.81 |
| 025-002-00700-0000 | 9.00 | \$ | - | \$ | 30.64 | \$ | - | \$ | 30.64 | \$ | - | \$ | 30.64 |
| 025-002-00800-0000 | 28.00 | \$ | 28.00 | \$ | 95.33 | \$ | 95.33 | \$ | - | \$ | 28.83 | \$ | 66.50 |
| 025-002-01000-0000 | 2.00 | \$ | 2.00 | \$ | 6.81 | \$ | 6.81 | \$ | - | \$ | 2.06 | \$ | 4.75 |
| 025-002-24300-0000 | 2.14 | \$ | - | \$ | 7.29 | \$ | - | \$ | 7.29 | \$ | - | \$ | 7.29 |
| 025-002-24310-0000 | 17.20 | \$ | 17.20 | \$ | 58.56 | \$ | 58.56 | \$ | - | \$ | 17.71 | \$ | 40.85 |
| 025-002-24312-0000 | 0.66 | \$ | - | \$ | 2.25 | \$ | - | \$ | 2.25 | \$ | - | \$ | 2.25 |
| 025-002-24400-0000 | 1.00 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 |
| 025-002-24500-0000 | 17.00 | \$ | - | \$ | 57.88 | \$ | - | \$ | 57.88 | \$ | - | \$ | 57.88 |
| 025-002-24600-0000 | 1.00 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 |
| 025-002-24700-0000 | 40.00 | \$ | 40.00 | \$ | 136.18 | \$ | 136.18 | \$ | - | \$ | 41.18 | \$ | 95.00 |
| 025-002-24800-0000 | 2.00 | \$ | - | \$ | 6.81 | \$ | - | \$ | 6.81 | \$ | - | \$ | 6.81 |
| 025-002-25000-0000 | 40.00 | \$ | 40.00 | \$ | 136.18 | \$ | 136.18 | \$ | - | \$ | 41.18 | \$ | 95.00 |
| 025-002-28000-0000 | 1.00 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 | \$ | - | \$ | 3.40 |
| 025-002-28100-0000 | 12.00 | \$ | 12.00 | \$ | 40.85 | \$ | 40.85 | \$ | - | \$ | 12.35 | \$ | 28.50 |
| 025-002-28400-0000 | 30.00 | \$ | 30.00 | \$ | 102.13 | \$ | 102.13 | \$ | - | \$ | 30.88 | \$ | 71.25 |
| 025-002-28500-0000 | 30.00 | \$ | 30.00 | \$ | 102.13 | \$ | 102.13 | \$ | - | \$ | 30.88 | \$ | 71.25 |
| 025-002-28600-0000 | 30.00 | \$ | 30.00 | \$ | 102.13 | \$ | 102.13 | \$ | - | \$ | 30.88 | \$ | 71.25 |
| 025-002-28700-0000 | 30.00 | \$ | 30.00 | \$ | 102.13 | \$ | 102.13 | \$ | - | \$ | 30.88 | \$ | 71.25 |
| 025-002-28800-0000 | 15.00 | \$ | 15.00 | \$ | 51.07 | \$ | 51.07 | \$ | - | \$ | 15.44 | \$ | 35.63 |
| 025-002-28900-0000 | 2.00 | \$ | 2.00 | \$ | 6.81 | \$ | 6.81 | \$ | - | \$ | 2.10 | \$ | 4.71 |
| Haldimand County | 2.00 | \$ | - | \$ | 6.81 | \$ | - | \$ | 6.81 | \$ | - | \$ | 6.81 |
| Haldimand County | 360.00 | \$ | - | \$ | 1,225.77 | \$ | - | \$ | 1,225.77 | \$ | - | \$ | 1,225.77 |
| Haldimand County | 2.00 | \$ | - | \$ | 6.81 | \$ | - | \$ | 6.81 | \$ | - | \$ | 6.81 |
| | \$ 2,176.00 | \$ | 1,101.66 | \$ | 7,408.13 | \$ | 3,750.56 | \$ | 3,657.57 | \$ | 1,134.20 | \$ | 6,273.93 |
| | | | | | | | | | | Haldimand County | | | \$ 1,239.39 |
| | | | | | | | | | | Amounts to be Billed | | | \$ 5,034.54 |

Project Name: Horseshoe Bay Main Branch

| | | | | | |
|---------------------------|--------------------------------|--------------------------------|--------------------------------------|--|-----------------------|
| Final Project Cost | Additional County Costs | Total Report Assessment | Total Agricultural Assessment | Pro Rated Agricultural Assessment | Grant Received |
| \$25,480.65 | | \$1.00 | \$0.09 | \$2,450.07 | \$816.69 |

| Roll Number | Total Assessment | Agricultural Lands Assessed (\$) | Gross Costs (\$) | Agricultural Lands Assessed (\$) | Non Agricultural Lands Assessed (\$) | Grant Received (\$) | Net Assessment (\$) |
|------------------------|------------------|----------------------------------|---------------------|----------------------------------|--------------------------------------|---------------------|---------------------|
| 021-002-21500-0000 | 0.01582 | \$ 0.02 | \$ 490.01 | \$ 490.01 | \$ - | \$ 163.34 | \$ 326.67 |
| 021-002-21600-0000 | 0.03574 | \$ 0.04 | \$ 980.03 | \$ 980.03 | \$ - | \$ 326.68 | \$ 653.35 |
| 021-002-34050-0000 | 0.00005 | \$ - | \$ - | \$ - | \$ - | \$ - | \$ - |
| 021-002-34200-0000 | 0.00029 | \$ - | \$ - | \$ - | \$ - | \$ - | \$ - |
| 021-002-34400-0000 | 0.00029 | \$ - | \$ - | \$ - | \$ - | \$ - | \$ - |
| 021-002-34450-0000 | 0.00003 | \$ - | \$ - | \$ - | \$ - | \$ - | \$ - |
| 021-002-34600-0000 | 0.00059 | \$ - | \$ - | \$ - | \$ - | \$ - | \$ - |
| 021-002-34700-0000 | 0.00005 | \$ - | \$ - | \$ - | \$ - | \$ - | \$ - |
| 021-002-34800-0000 | 0.00005 | \$ - | \$ - | \$ - | \$ - | \$ - | \$ - |
| 021-002-35000-0000 | 0.00003 | \$ - | \$ - | \$ - | \$ - | \$ - | \$ - |
| 021-002-35100-0000 | 0.17570 | \$ - | \$ 4,410.11 | \$ - | \$ 4,410.11 | \$ - | \$ 4,410.11 |
| 021-002-35105-0000 | 0.05020 | \$ - | \$ 1,225.03 | \$ - | \$ 1,225.03 | \$ - | \$ 1,225.03 |
| 021-002-35106-0000 | 0.03520 | \$ - | \$ 980.03 | \$ - | \$ 980.03 | \$ - | \$ 980.03 |
| 021-002-35108-0000 | 0.05020 | \$ - | \$ 1,225.03 | \$ - | \$ 1,225.03 | \$ - | \$ 1,225.03 |
| 021-002-35109-0000 | 0.02510 | \$ - | \$ 735.02 | \$ - | \$ 735.02 | \$ - | \$ 735.02 |
| 021-002-35110-0000 | 0.00099 | \$ - | \$ - | \$ - | \$ - | \$ - | \$ - |
| 021-002-35111-0000 | 0.02510 | \$ - | \$ 735.02 | \$ - | \$ 735.02 | \$ - | \$ 735.02 |
| 021-002-35113-0000 | 0.03520 | \$ - | \$ 980.03 | \$ - | \$ 980.03 | \$ - | \$ 980.03 |
| 021-002-35122-0000 | 0.02510 | \$ - | \$ 735.02 | \$ - | \$ 735.02 | \$ - | \$ 735.02 |
| 021-002-35124-0000 | 0.02510 | \$ - | \$ 735.02 | \$ - | \$ 735.02 | \$ - | \$ 735.02 |
| 021-002-35150-0000 | 0.00603 | \$ - | \$ 245.01 | \$ - | \$ 245.01 | \$ - | \$ 245.01 |
| 021-002-35160-0000 | 0.03673 | \$ 0.04 | \$ 980.03 | \$ 980.03 | \$ - | \$ 326.67 | \$ 653.36 |
| 021-002-35200-0000 | 0.12780 | \$ - | \$ 3,185.08 | \$ - | \$ 3,185.08 | \$ - | \$ 3,185.08 |
| 021-002-35210-0000 | 0.00011 | \$ - | \$ - | \$ - | \$ - | \$ - | \$ - |
| 021-002-37300-0000 | 0.00075 | \$ - | \$ - | \$ - | \$ - | \$ - | \$ - |
| 021-002-37400-0000 | 0.02954 | 0.00 | \$ 735.02 | \$ - | \$ 735.02 | \$ - | \$ 735.02 |
| 021-002-37451-0000 | 0.08365 | 0.00 | \$ 1,960.05 | \$ - | \$ 1,960.05 | \$ - | \$ 1,960.05 |
| Haldimand County Roads | 0.09000 | 0.00 | \$ 2,205.06 | \$ - | \$ 2,205.06 | \$ - | \$ 2,205.06 |
| Haldimand County Roads | 0.11032 | 0.00 | \$ 2,695.07 | \$ - | \$ 2,695.07 | \$ - | \$ 2,695.07 |
| Haldimand County Roads | 0.01442 | 0.00 | \$ 244.98 | \$ - | \$ 244.98 | \$ - | \$ 244.98 |
| | 1.00 | \$ 0.09 | \$ 25,480.65 | \$ 2,450.07 | \$ 23,030.58 | \$ 816.69 | \$ 24,663.96 |
| | | | | | Haldimand County | | \$ 5,145.11 |
| | | | | | Amounts to be Billed | | \$ 19,518.85 |

Project Name: James Main Maintenance

| | | | | | |
|---------------------------|--------------------------------|--------------------------------|--------------------------------------|--|-----------------------|
| Final Project Cost | Additional County Costs | Total Report Assessment | Total Agricultural Assessment | Pro Rated Agricultural Assessment | Grant Received |
| \$19,619.32 | \$0.00 | \$24,282.98 | \$20,321.07 | \$16,418.33 | \$5,472.77 |

| Roll Number | Total Assessment | Agricultural Lands Assessed (\$) | Gross Costs (\$) | Agricultural Lands Assessed (\$) | Non Agricultural Lands Assessed (\$) | Grant Received (\$) | Net Assessment (\$) |
|--------------------|------------------|----------------------------------|------------------|----------------------------------|--------------------------------------|---------------------|---------------------|
| 022-002-02000-0000 | \$ 12.00 | \$ - | \$ 9.70 | \$ - | \$ 9.70 | \$ - | \$ 9.70 |
| 022-002-05000-0000 | \$ 459.00 | \$ 459.00 | \$ 370.85 | \$ 370.85 | \$ - | \$ 123.62 | \$ 247.23 |
| 022-002-05300-0000 | \$ 958.00 | \$ 958.00 | \$ 774.01 | \$ 774.01 | \$ - | \$ 258.00 | \$ 516.01 |
| 022-002-05600-0000 | \$ 1,001.00 | \$ 1,001.00 | \$ 808.75 | \$ 808.75 | \$ - | \$ 269.58 | \$ 539.17 |
| 022-002-06300-0000 | \$ 1,055.00 | \$ 1,055.00 | \$ 852.38 | \$ 852.38 | \$ - | \$ 284.13 | \$ 568.25 |
| 022-002-06400-0000 | \$ 981.00 | \$ 981.00 | \$ 792.59 | \$ 792.59 | \$ - | \$ 264.20 | \$ 528.39 |
| 022-002-06600-0000 | \$ 1,065.00 | \$ 1,065.00 | \$ 860.46 | \$ 860.46 | \$ - | \$ 286.82 | \$ 573.64 |
| 022-002-06700-0000 | \$ 932.00 | \$ 932.00 | \$ 753.01 | \$ 753.01 | \$ - | \$ 251.00 | \$ 502.01 |
| 022-002-07000-0000 | \$ 799.00 | \$ - | \$ 645.55 | \$ - | \$ 645.55 | \$ - | \$ 645.55 |
| 022-002-07100-0000 | \$ 506.00 | \$ 506.00 | \$ 408.82 | \$ 408.82 | \$ - | \$ 136.27 | \$ 272.55 |
| 022-002-07500-0000 | \$ 531.00 | \$ 531.00 | \$ 429.02 | \$ 429.02 | \$ - | \$ 143.01 | \$ 286.01 |
| 022-003-01200-0000 | \$ 723.00 | \$ - | \$ 584.14 | \$ - | \$ 584.14 | \$ - | \$ 584.14 |
| 022-003-01300-0000 | \$ 526.00 | \$ 526.00 | \$ 424.98 | \$ 424.98 | \$ - | \$ 141.66 | \$ 283.32 |
| 022-003-01600-0000 | \$ 677.00 | \$ 677.00 | \$ 546.98 | \$ 546.98 | \$ - | \$ 182.33 | \$ 364.65 |
| 022-003-01700-0000 | \$ 1,280.00 | \$ 1,280.00 | \$ 1,034.17 | \$ 1,034.17 | \$ - | \$ 344.72 | \$ 689.45 |
| 022-003-01800-0000 | \$ 642.00 | \$ 642.00 | \$ 518.70 | \$ 518.70 | \$ - | \$ 172.90 | \$ 345.80 |
| 022-003-01850-0000 | \$ 18.00 | \$ - | \$ 14.54 | \$ - | \$ 14.54 | \$ - | \$ 14.54 |
| 022-003-01900-0000 | \$ 659.00 | \$ 659.00 | \$ 532.44 | \$ 532.44 | \$ - | \$ 177.48 | \$ 354.96 |
| 022-003-02100-0000 | \$ 699.00 | \$ 699.00 | \$ 564.75 | \$ 564.75 | \$ - | \$ 188.25 | \$ 376.50 |
| 022-003-02110-0000 | \$ 42.00 | \$ - | \$ 33.93 | \$ - | \$ 33.93 | \$ - | \$ 33.93 |
| 022-003-02150-0000 | \$ 105.00 | \$ - | \$ 84.83 | \$ - | \$ 84.83 | \$ - | \$ 84.83 |
| 022-003-02300-0000 | \$ 547.00 | \$ 547.00 | \$ 441.95 | \$ 441.95 | \$ - | \$ 147.32 | \$ 294.63 |
| 022-003-02400-0000 | \$ 1,412.00 | \$ 1,412.00 | \$ 1,140.82 | \$ 1,140.82 | \$ - | \$ 380.27 | \$ 760.55 |
| 022-003-02410-0000 | \$ 21.00 | \$ - | \$ 16.97 | \$ - | \$ 16.97 | \$ - | \$ 16.97 |
| 022-003-02600-0000 | \$ 4.00 | \$ - | \$ 3.23 | \$ - | \$ 3.23 | \$ - | \$ 3.23 |
| 022-003-02700-0000 | \$ 165.50 | \$ 165.50 | \$ 133.71 | \$ 133.71 | \$ - | \$ 44.57 | \$ 89.14 |
| 022-003-02800-0000 | \$ 4.50 | \$ - | \$ 3.64 | \$ - | \$ 3.64 | \$ - | \$ 3.64 |
| 022-003-02900-0000 | \$ 4.00 | \$ - | \$ 3.23 | \$ - | \$ 3.23 | \$ - | \$ 3.23 |
| 022-003-02910-0000 | \$ 4.00 | \$ - | \$ 3.23 | \$ - | \$ 3.23 | \$ - | \$ 3.23 |
| 022-003-03000-0000 | \$ 4.00 | \$ - | \$ 3.23 | \$ - | \$ 3.23 | \$ - | \$ 3.23 |
| 022-003-03100-0000 | \$ 3.00 | \$ - | \$ 2.42 | \$ - | \$ 2.42 | \$ - | \$ 2.42 |
| 022-003-03200-0000 | \$ 194.00 | \$ 194.00 | \$ 156.74 | \$ 156.74 | \$ - | \$ 52.25 | \$ 104.49 |
| 022-003-03300-0000 | \$ 4.00 | \$ - | \$ 3.23 | \$ - | \$ 3.23 | \$ - | \$ 3.23 |
| 022-003-03400-0000 | \$ 3.00 | \$ - | \$ 2.42 | \$ - | \$ 2.42 | \$ - | \$ 2.42 |
| 022-003-03500-0000 | \$ 4.00 | \$ - | \$ 3.23 | \$ - | \$ 3.23 | \$ - | \$ 3.23 |
| 022-003-03700-0000 | \$ 2.00 | \$ - | \$ 1.62 | \$ - | \$ 1.62 | \$ - | \$ 1.62 |
| 022-003-03750-0000 | \$ 12.00 | \$ - | \$ 9.70 | \$ - | \$ 9.70 | \$ - | \$ 9.70 |
| 022-003-03800-0000 | \$ 97.90 | \$ 97.90 | \$ 79.10 | \$ 79.10 | \$ - | \$ 26.37 | \$ 52.73 |
| 022-003-03805-0000 | \$ 2.62 | \$ - | \$ 2.12 | \$ - | \$ 2.12 | \$ - | \$ 2.12 |
| 022-003-03810-0000 | \$ 2.00 | \$ - | \$ 1.62 | \$ - | \$ 1.62 | \$ - | \$ 1.62 |
| 022-003-03820-0000 | \$ 2.48 | \$ - | \$ 2.00 | \$ - | \$ 2.00 | \$ - | \$ 2.00 |
| 022-003-03900-0000 | \$ 4.00 | \$ - | \$ 3.23 | \$ - | \$ 3.23 | \$ - | \$ 3.23 |
| 022-003-04000-0000 | \$ 2.00 | \$ - | \$ 1.62 | \$ - | \$ 1.62 | \$ - | \$ 1.62 |
| 022-003-04100-0000 | \$ 39.00 | \$ 39.00 | \$ 31.51 | \$ 31.51 | \$ - | \$ 10.50 | \$ 21.01 |
| 022-003-04200-0000 | \$ 2.00 | \$ - | \$ 1.62 | \$ - | \$ 1.62 | \$ - | \$ 1.62 |
| 022-003-04210-0000 | \$ 7.00 | \$ - | \$ 5.66 | \$ - | \$ 5.66 | \$ - | \$ 5.66 |
| 022-003-04220-0000 | \$ 3.00 | \$ - | \$ 2.42 | \$ - | \$ 2.42 | \$ - | \$ 2.42 |
| 022-003-04300-0000 | \$ 2.00 | \$ - | \$ 1.62 | \$ - | \$ 1.62 | \$ - | \$ 1.62 |
| 022-003-04310-0000 | \$ 2.00 | \$ - | \$ 1.62 | \$ - | \$ 1.62 | \$ - | \$ 1.62 |
| 022-003-04320-0000 | \$ 2.00 | \$ - | \$ 1.62 | \$ - | \$ 1.62 | \$ - | \$ 1.62 |
| 022-003-04400-0000 | \$ 4.00 | \$ - | \$ 3.23 | \$ - | \$ 3.23 | \$ - | \$ 3.23 |
| 022-003-04500-0000 | \$ 11.00 | \$ 11.00 | \$ 8.89 | \$ 8.89 | \$ - | \$ 2.96 | \$ 5.93 |
| 022-003-04510-0000 | \$ 5.00 | \$ 5.00 | \$ 4.04 | \$ 4.04 | \$ - | \$ 1.35 | \$ 2.69 |
| 022-003-07915-0000 | \$ 53.00 | \$ - | \$ 42.82 | \$ - | \$ 42.82 | \$ - | \$ 42.82 |
| 022-003-07920-0000 | \$ 12.00 | \$ - | \$ 9.70 | \$ - | \$ 9.70 | \$ - | \$ 9.70 |
| 022-003-07950-0000 | \$ 273.00 | \$ 273.00 | \$ 220.57 | \$ 220.57 | \$ - | \$ 73.52 | \$ 147.05 |
| 022-003-08600-0000 | \$ 981.92 | \$ 981.92 | \$ 793.34 | \$ 793.34 | \$ - | \$ 264.45 | \$ 528.89 |
| 022-003-08610-0000 | \$ 26.06 | \$ - | \$ 21.06 | \$ - | \$ 21.06 | \$ - | \$ 21.06 |
| 022-003-08700-0000 | \$ 158.00 | \$ 158.00 | \$ 127.66 | \$ 127.66 | \$ - | \$ 42.55 | \$ 85.11 |
| 022-003-08720-0000 | \$ 60.00 | \$ 60.00 | \$ 48.48 | \$ 48.48 | \$ - | \$ 16.16 | \$ 32.32 |
| 022-003-08800-0000 | \$ 1,144.00 | \$ 1,144.00 | \$ 924.29 | \$ 924.29 | \$ - | \$ 308.10 | \$ 616.19 |
| 022-003-08900-0000 | \$ 19.00 | \$ - | \$ 15.35 | \$ - | \$ 15.35 | \$ - | \$ 15.35 |
| 022-003-09000-0000 | \$ 234.00 | \$ 234.00 | \$ 189.06 | \$ 189.06 | \$ - | \$ 63.02 | \$ 126.04 |

| Roll Number | Total Assessment | Agricultural Lands Assessed (\$) | Gross Costs (\$) | Agricultural Lands Assessed (\$) | Non Agricultural Lands Assessed (\$) | Grant Received (\$) | Net Assessment (\$) |
|--------------------|---------------------|----------------------------------|---------------------|----------------------------------|--------------------------------------|---------------------|---------------------|
| 022-003-09300-0000 | \$ 2,548.00 | \$ 2,548.00 | \$ 2,058.64 | \$ 2,058.64 | \$ - | \$ 686.21 | \$ 1,372.43 |
| 023-001-01200-0000 | \$ 10.00 | \$ - | \$ 8.08 | \$ - | \$ 8.08 | \$ - | \$ 8.08 |
| 023-001-01300-0000 | \$ 9.00 | \$ - | \$ 7.27 | \$ - | \$ 7.27 | \$ - | \$ 7.27 |
| 023-001-01400-0000 | \$ 5.25 | \$ - | \$ 4.24 | \$ - | \$ 4.24 | \$ - | \$ 4.24 |
| 023-001-01500-0000 | \$ 355.75 | \$ 355.75 | \$ 287.43 | \$ 287.43 | \$ - | \$ 95.81 | \$ 191.62 |
| 023-001-02200-0000 | \$ 25.00 | \$ 25.00 | \$ 20.20 | \$ 20.20 | \$ - | \$ 6.73 | \$ 13.47 |
| 023-001-02300-0000 | \$ 32.00 | \$ - | \$ 25.85 | \$ - | \$ 25.85 | \$ - | \$ 25.85 |
| 023-001-02400-0000 | \$ 4.00 | \$ - | \$ 3.23 | \$ - | \$ 3.23 | \$ - | \$ 3.23 |
| 023-001-02450-0000 | \$ 8.00 | \$ - | \$ 6.46 | \$ - | \$ 6.46 | \$ - | \$ 6.46 |
| 023-001-02500-0000 | \$ 56.00 | \$ 56.00 | \$ 45.24 | \$ 45.24 | \$ - | \$ 15.08 | \$ 30.16 |
| 023-001-02510-0000 | \$ 14.00 | \$ - | \$ 11.31 | \$ - | \$ 11.31 | \$ - | \$ 11.31 |
| 023-001-02600-0000 | \$ 30.00 | \$ - | \$ 24.24 | \$ - | \$ 24.24 | \$ - | \$ 24.24 |
| 023-001-02690-0000 | \$ 4.00 | \$ - | \$ 3.23 | \$ - | \$ 3.23 | \$ - | \$ 3.23 |
| 023-001-02700-0000 | \$ 7.00 | \$ - | \$ 5.66 | \$ - | \$ 5.66 | \$ - | \$ 5.66 |
| 023-001-02750-0000 | \$ 8.00 | \$ - | \$ 6.46 | \$ - | \$ 6.46 | \$ - | \$ 6.46 |
| 023-001-02770-0000 | \$ 4.00 | \$ - | \$ 3.23 | \$ - | \$ 3.23 | \$ - | \$ 3.23 |
| 023-001-02800-0000 | \$ 3.00 | \$ - | \$ 2.42 | \$ - | \$ 2.42 | \$ - | \$ 2.42 |
| 023-001-02810-0000 | \$ 3.00 | \$ - | \$ 2.42 | \$ - | \$ 2.42 | \$ - | \$ 2.42 |
| 023-001-02910-0000 | \$ 5.00 | \$ - | \$ 4.04 | \$ - | \$ 4.04 | \$ - | \$ 4.04 |
| 023-001-02950-0000 | \$ 15.00 | \$ - | \$ 12.12 | \$ - | \$ 12.12 | \$ - | \$ 12.12 |
| 023-001-02952-0000 | \$ 1.50 | \$ - | \$ 1.21 | \$ - | \$ 1.21 | \$ - | \$ 1.21 |
| 023-001-02954-0000 | \$ 1.50 | \$ - | \$ 1.21 | \$ - | \$ 1.21 | \$ - | \$ 1.21 |
| 023-001-03000-0000 | \$ 9.00 | \$ - | \$ 7.27 | \$ - | \$ 7.27 | \$ - | \$ 7.27 |
| 023-001-03100-0000 | \$ 3.00 | \$ - | \$ 2.42 | \$ - | \$ 2.42 | \$ - | \$ 2.42 |
| 023-001-03200-0000 | \$ 4.00 | \$ - | \$ 3.23 | \$ - | \$ 3.23 | \$ - | \$ 3.23 |
| 023-001-03400-0000 | \$ 3.00 | \$ - | \$ 2.42 | \$ - | \$ 2.42 | \$ - | \$ 2.42 |
| 023-001-03450-0000 | \$ 3.00 | \$ - | \$ 2.42 | \$ - | \$ 2.42 | \$ - | \$ 2.42 |
| 023-001-03500-0000 | \$ 7.00 | \$ - | \$ 5.66 | \$ - | \$ 5.66 | \$ - | \$ 5.66 |
| 023-001-03600-0000 | \$ 2.00 | \$ - | \$ 1.62 | \$ - | \$ 1.62 | \$ - | \$ 1.62 |
| 023-001-03700-0000 | \$ 9.00 | \$ - | \$ 7.27 | \$ - | \$ 7.27 | \$ - | \$ 7.27 |
| 023-001-03710-0000 | \$ 5.06 | \$ - | \$ 4.09 | \$ - | \$ 4.09 | \$ - | \$ 4.09 |
| 023-001-03800-0000 | \$ 1.94 | \$ - | \$ 1.57 | \$ - | \$ 1.57 | \$ - | \$ 1.57 |
| 023-001-03810-0000 | \$ 2.00 | \$ - | \$ 1.62 | \$ - | \$ 1.62 | \$ - | \$ 1.62 |
| 023-001-03820-0000 | \$ 2.00 | \$ - | \$ 1.62 | \$ - | \$ 1.62 | \$ - | \$ 1.62 |
| 023-001-03830-0000 | \$ 2.00 | \$ - | \$ 1.62 | \$ - | \$ 1.62 | \$ - | \$ 1.62 |
| 023-001-03910-0000 | \$ 26.00 | \$ 26.00 | \$ 21.01 | \$ 21.01 | \$ - | \$ 7.00 | \$ 14.01 |
| 023-001-03921-0000 | \$ 1.76 | \$ - | \$ 1.42 | \$ - | \$ 1.42 | \$ - | \$ 1.42 |
| 023-001-03922-0000 | \$ 1.86 | \$ - | \$ 1.50 | \$ - | \$ 1.50 | \$ - | \$ 1.50 |
| 023-001-03923-0000 | \$ 1.88 | \$ - | \$ 1.52 | \$ - | \$ 1.52 | \$ - | \$ 1.52 |
| 023-001-03924-0000 | \$ 1.86 | \$ - | \$ 1.50 | \$ - | \$ 1.50 | \$ - | \$ 1.50 |
| 023-001-03925-0000 | \$ 1.97 | \$ - | \$ 1.59 | \$ - | \$ 1.59 | \$ - | \$ 1.59 |
| 023-001-03926-0000 | \$ 1.75 | \$ - | \$ 1.41 | \$ - | \$ 1.41 | \$ - | \$ 1.41 |
| 023-001-03927-0000 | \$ 1.76 | \$ - | \$ 1.42 | \$ - | \$ 1.42 | \$ - | \$ 1.42 |
| 023-001-03928-0000 | \$ 1.81 | \$ - | \$ 1.46 | \$ - | \$ 1.46 | \$ - | \$ 1.46 |
| 023-001-03929-0000 | \$ 1.75 | \$ - | \$ 1.41 | \$ - | \$ 1.41 | \$ - | \$ 1.41 |
| 023-001-03930-0000 | \$ 1.75 | \$ - | \$ 1.41 | \$ - | \$ 1.41 | \$ - | \$ 1.41 |
| 023-001-03931-0000 | \$ 1.63 | \$ - | \$ 1.32 | \$ - | \$ 1.32 | \$ - | \$ 1.32 |
| 023-001-03932-0000 | \$ 1.22 | \$ - | \$ 0.99 | \$ - | \$ 0.99 | \$ - | \$ 0.99 |
| 023-005-00100-0000 | \$ 1.00 | \$ - | \$ 0.81 | \$ - | \$ 0.81 | \$ - | \$ 0.81 |
| 023-005-00102-0000 | \$ 1.00 | \$ - | \$ 0.81 | \$ - | \$ 0.81 | \$ - | \$ 0.81 |
| 023-005-00104-0000 | \$ 2.00 | \$ - | \$ 1.62 | \$ - | \$ 1.62 | \$ - | \$ 1.62 |
| 023-005-00150-0000 | \$ 17.00 | \$ 17.00 | \$ 13.74 | \$ 13.74 | \$ - | \$ 4.58 | \$ 9.16 |
| 023-005-00400-0000 | \$ 16.00 | \$ - | \$ 12.93 | \$ - | \$ 12.93 | \$ - | \$ 12.93 |
| Haldimand County | \$ 1,576.00 | \$ - | \$ 1,273.31 | \$ - | \$ 1,273.31 | \$ - | \$ 1,273.31 |
| Haldimand County | \$ 214.00 | \$ - | \$ 172.90 | \$ - | \$ 172.90 | \$ - | \$ 172.90 |
| | \$ 24,282.98 | \$ 20,321.07 | \$ 19,619.32 | \$ 16,418.33 | \$ 3,200.99 | \$ 5,472.77 | \$ 14,146.55 |
| | | | | | Haldimand County | | \$ 1,446.21 |
| | | | | | Amounts to be Billed | | \$ 12,700.34 |

Project Name: Waines Maintenance

| | | | | | |
|---------------------------|--------------------------------|--------------------------------|--------------------------------------|--|-----------------------|
| Final Project Cost | Additional County Costs | Total Report Assessment | Total Agricultural Assessment | Pro Rated Agricultural Assessment | Grant Received |
| \$15,816.05 | | \$39,140.00 | \$33,635.46 | \$13,591.74 | \$4,530.58 |

| Roll Number | Total Assessment | Agricultural Lands Assessed (\$) | Gross Costs (\$) | Agricultural Lands Assessed (\$) | Non Agricultural Lands Assessed (\$) | Grant Received (\$) | Net Assessment (\$) |
|--------------------|---------------------|----------------------------------|---------------------|----------------------------------|--------------------------------------|---------------------|---------------------|
| 022-002-05000-0000 | \$ 1,427.00 | \$ 1,427.00 | \$ 576.64 | \$ 576.64 | \$ - | \$ 192.21 | \$ 384.43 |
| 022-002-05300-0000 | \$ 2,292.00 | \$ 2,292.00 | \$ 926.17 | \$ 926.17 | \$ - | \$ 308.72 | \$ 617.45 |
| 022-002-05600-0000 | \$ 1,786.00 | \$ 1,786.00 | \$ 721.70 | \$ 721.70 | \$ - | \$ 240.57 | \$ 481.13 |
| 022-002-06300-0000 | \$ 1,292.00 | \$ 1,292.00 | \$ 522.08 | \$ 522.08 | \$ - | \$ 174.03 | \$ 348.05 |
| 022-002-06400-0000 | \$ 816.00 | \$ 816.00 | \$ 329.74 | \$ 329.74 | \$ - | \$ 109.91 | \$ 219.83 |
| 022-003-01200-0000 | \$ 2,507.00 | \$ - | \$ 1,013.05 | \$ - | \$ 1,013.05 | \$ - | \$ 1,013.05 |
| 022-003-01300-0000 | \$ 5,048.00 | \$ 5,048.00 | \$ 2,039.84 | \$ 2,039.84 | \$ - | \$ 679.95 | \$ 1,359.89 |
| 022-003-01600-0000 | \$ 4,245.00 | \$ 4,245.00 | \$ 1,715.36 | \$ 1,715.36 | \$ - | \$ 571.79 | \$ 1,143.57 |
| 022-003-01700-0000 | \$ 2,971.00 | \$ 2,971.00 | \$ 1,200.55 | \$ 1,200.55 | \$ - | \$ 400.18 | \$ 800.37 |
| 022-003-01800-0000 | \$ 2,816.40 | \$ 2,816.40 | \$ 1,138.08 | \$ 1,138.08 | \$ - | \$ 379.36 | \$ 758.72 |
| 022-003-01850-0000 | \$ 128.60 | \$ - | \$ 51.97 | \$ - | \$ 51.97 | \$ - | \$ 51.97 |
| 022-003-01900-0000 | \$ 2,538.00 | \$ 2,538.00 | \$ 1,025.58 | \$ 1,025.58 | \$ - | \$ 341.86 | \$ 683.72 |
| 022-003-02000-0000 | \$ 10.00 | \$ - | \$ 4.04 | \$ - | \$ 4.04 | \$ - | \$ 4.04 |
| 022-003-02100-0000 | \$ 2,775.00 | \$ 2,775.00 | \$ 1,121.35 | \$ 1,121.35 | \$ - | \$ 373.78 | \$ 747.57 |
| 022-003-02110-0000 | \$ 239.00 | \$ - | \$ 96.58 | \$ - | \$ 96.58 | \$ - | \$ 96.58 |
| 022-003-02150-0000 | \$ 1,623.00 | \$ - | \$ 655.84 | \$ - | \$ 655.84 | \$ - | \$ 655.84 |
| 022-003-02300-0000 | \$ 763.00 | \$ 763.00 | \$ 308.32 | \$ 308.32 | \$ - | \$ 102.77 | \$ 205.55 |
| 022-003-08600-0000 | \$ 2,817.00 | \$ 2,817.00 | \$ 1,138.32 | \$ 1,138.32 | \$ - | \$ 379.44 | \$ 758.88 |
| 022-003-08800-0000 | \$ 1,579.00 | \$ 1,579.00 | \$ 638.06 | \$ 638.06 | \$ - | \$ 212.69 | \$ 425.37 |
| 023-001-01200-0000 | \$ 7.00 | \$ - | \$ 2.83 | \$ - | \$ 2.83 | \$ - | \$ 2.83 |
| 023-001-01300-0000 | \$ 12.00 | \$ - | \$ 4.85 | \$ - | \$ 4.85 | \$ - | \$ 4.85 |
| 023-001-01400-0000 | \$ 6.94 | \$ - | \$ 2.80 | \$ - | \$ 2.80 | \$ - | \$ 2.80 |
| 023-001-01500-0000 | \$ 470.06 | \$ 470.06 | \$ 189.95 | \$ 189.95 | \$ - | \$ 63.32 | \$ 126.63 |
| Haldimand County | \$ 645.00 | \$ - | \$ 260.64 | \$ - | \$ 260.64 | \$ - | \$ 260.64 |
| Haldimand County | \$ 22.00 | \$ - | \$ 8.89 | \$ - | \$ 8.89 | \$ - | \$ 8.89 |
| Haldimand County | \$ 304.00 | \$ - | \$ 122.82 | \$ - | \$ 122.82 | \$ - | \$ 122.82 |
| | \$ 39,140.00 | \$ 33,635.46 | \$ 15,816.05 | \$ 13,591.74 | \$ 2,224.31 | \$ 4,530.58 | \$ 11,285.47 |
| | | | | | Haldimand County | | \$ 392.35 |
| | | | | | Amounts to be Billed | | \$ 10,893.12 |

Project Name: Boulton Maintenance

| | | | | | |
|---------------------------|--------------------------------|--------------------------------|--------------------------------------|--|-----------------------|
| Final Project Cost | Additional County Costs | Total Report Assessment | Total Agricultural Assessment | Pro Rated Agricultural Assessment | Grant Received |
| \$10,285.27 | \$0.00 | \$23,000.86 | \$17,315.66 | \$7,750.35 | \$2,526.83 |

| Roll Number | Total Assessment | Agricultural Lands Assessed (\$) | Gross Costs (\$) | Agricultural Lands Assessed (\$) | Non Agricultural Lands Assessed (\$) | Grant Received (\$) | Net Assessment (\$) |
|--------------------|------------------|----------------------------------|------------------|----------------------------------|--------------------------------------|---------------------|---------------------|
| 023-002-04200-0000 | \$ 1.57 | \$ - | \$ 0.70 | \$ - | \$ 0.70 | \$ - | \$ 0.70 |
| 023-002-04300-0000 | \$ 1.57 | \$ - | \$ 0.70 | \$ - | \$ 0.70 | \$ - | \$ 0.70 |
| 023-002-04400-0000 | \$ 4.70 | \$ - | \$ 2.10 | \$ - | \$ 2.10 | \$ - | \$ 2.10 |
| 023-002-05500-0000 | \$ 1.57 | \$ - | \$ 0.70 | \$ - | \$ 0.70 | \$ - | \$ 0.70 |
| 023-002-05800-0000 | \$ 1.57 | \$ - | \$ 0.70 | \$ - | \$ 0.70 | \$ - | \$ 0.70 |
| 023-002-09200-0000 | \$ 1.57 | \$ - | \$ 0.70 | \$ - | \$ 0.70 | \$ - | \$ 0.70 |
| 023-002-12100-0000 | \$ 4.70 | \$ - | \$ 2.10 | \$ - | \$ 2.10 | \$ - | \$ 2.10 |
| 023-002-12800-0000 | \$ 3.13 | \$ - | \$ 1.40 | \$ - | \$ 1.40 | \$ - | \$ 1.40 |
| 023-002-12900-0000 | \$ 1.57 | \$ - | \$ 0.70 | \$ - | \$ 0.70 | \$ - | \$ 0.70 |
| 023-002-13000-0000 | \$ 1.57 | \$ - | \$ 0.70 | \$ - | \$ 0.70 | \$ - | \$ 0.70 |
| 023-002-13400-0000 | \$ 3.13 | \$ - | \$ 1.40 | \$ - | \$ 1.40 | \$ - | \$ 1.40 |
| 023-003-00600-0000 | \$ 4,159.58 | \$ 4,159.58 | \$ 1,860.03 | \$ 1,860.03 | \$ - | \$ 606.43 | \$ 1,253.60 |
| 023-003-01000-0000 | \$ 433.74 | \$ 433.74 | \$ 193.96 | \$ 193.96 | \$ - | \$ 63.24 | \$ 130.72 |
| 023-003-01800-0000 | \$ 204.49 | \$ 204.49 | \$ 91.44 | \$ 91.44 | \$ - | \$ 29.81 | \$ 61.63 |
| 023-003-01850-0000 | \$ 3.35 | \$ - | \$ 1.50 | \$ - | \$ 1.50 | \$ - | \$ 1.50 |
| 023-003-01900-0000 | \$ 188.56 | \$ - | \$ 84.32 | \$ - | \$ 84.32 | \$ - | \$ 84.32 |
| 023-003-02000-0000 | \$ 88.24 | \$ - | \$ 39.46 | \$ - | \$ 39.46 | \$ - | \$ 39.46 |
| 023-003-02100-0000 | \$ 95.03 | \$ - | \$ 42.49 | \$ - | \$ 42.49 | \$ - | \$ 42.49 |
| 023-003-02200-0000 | \$ 2.26 | \$ - | \$ 1.01 | \$ - | \$ 1.01 | \$ - | \$ 1.01 |
| 023-003-02300-0000 | \$ 43.29 | \$ 43.29 | \$ 19.36 | \$ 19.36 | \$ - | \$ 6.31 | \$ 13.05 |
| 023-003-02400-0000 | \$ 41.59 | \$ - | \$ 18.60 | \$ - | \$ 18.60 | \$ - | \$ 18.60 |
| 023-003-02500-0000 | \$ 84.88 | \$ 84.88 | \$ 37.96 | \$ 37.96 | \$ - | \$ 12.38 | \$ 25.58 |
| 023-003-02600-0000 | \$ 1.93 | \$ - | \$ 0.86 | \$ - | \$ 0.86 | \$ - | \$ 0.86 |
| 023-003-02610-0000 | \$ 1.93 | \$ - | \$ 0.86 | \$ - | \$ 0.86 | \$ - | \$ 0.86 |
| 023-003-02620-0000 | \$ 1.93 | \$ - | \$ 0.86 | \$ - | \$ 0.86 | \$ - | \$ 0.86 |
| 023-003-02700-0000 | \$ 3.36 | \$ - | \$ 1.50 | \$ - | \$ 1.50 | \$ - | \$ 1.50 |
| 023-003-02800-0000 | \$ 3.36 | \$ - | \$ 1.50 | \$ - | \$ 1.50 | \$ - | \$ 1.50 |
| 023-003-02900-0000 | \$ 61.06 | \$ 61.06 | \$ 27.30 | \$ 27.30 | \$ - | \$ 8.90 | \$ 18.40 |
| 023-003-03000-0000 | \$ 35.06 | \$ - | \$ 15.68 | \$ - | \$ 15.68 | \$ - | \$ 15.68 |
| 023-003-03100-0000 | \$ 24.32 | \$ - | \$ 10.88 | \$ - | \$ 10.88 | \$ - | \$ 10.88 |
| 023-003-03200-0000 | \$ 22.98 | \$ - | \$ 10.28 | \$ - | \$ 10.28 | \$ - | \$ 10.28 |
| 023-003-03300-0000 | \$ 20.47 | \$ - | \$ 9.15 | \$ - | \$ 9.15 | \$ - | \$ 9.15 |
| 023-003-03390-0000 | \$ 7.05 | \$ - | \$ 3.15 | \$ - | \$ 3.15 | \$ - | \$ 3.15 |
| 023-003-03400-0000 | \$ 7.19 | \$ - | \$ 3.22 | \$ - | \$ 3.22 | \$ - | \$ 3.22 |
| 023-003-03410-0000 | \$ 6.79 | \$ - | \$ 3.04 | \$ - | \$ 3.04 | \$ - | \$ 3.04 |
| 023-003-03500-0000 | \$ 19.12 | \$ - | \$ 8.55 | \$ - | \$ 8.55 | \$ - | \$ 8.55 |
| 023-003-03600-0000 | \$ 0.27 | \$ - | \$ 0.12 | \$ - | \$ 0.12 | \$ - | \$ 0.12 |
| 023-003-03700-0000 | \$ 1.88 | \$ - | \$ 0.84 | \$ - | \$ 0.84 | \$ - | \$ 0.84 |
| 023-003-03710-0000 | \$ 2.21 | \$ - | \$ 0.99 | \$ - | \$ 0.99 | \$ - | \$ 0.99 |
| 023-003-03800-0000 | \$ 1.96 | \$ - | \$ 0.88 | \$ - | \$ 0.88 | \$ - | \$ 0.88 |
| 023-003-03880-0000 | \$ 5.12 | \$ 5.12 | \$ 2.29 | \$ 2.29 | \$ - | \$ 0.75 | \$ 1.54 |
| 023-003-03900-0000 | \$ 186.71 | \$ 186.71 | \$ 83.49 | \$ 83.49 | \$ - | \$ 27.22 | \$ 56.27 |
| 023-003-04000-0000 | \$ 161.32 | \$ 161.32 | \$ 72.14 | \$ 72.14 | \$ - | \$ 23.52 | \$ 48.62 |
| 023-003-04010-0000 | \$ 3.23 | \$ - | \$ 1.44 | \$ - | \$ 1.44 | \$ - | \$ 1.44 |
| 023-003-04100-0000 | \$ 1.68 | \$ - | \$ 0.75 | \$ - | \$ 0.75 | \$ - | \$ 0.75 |
| 023-003-04200-0000 | \$ 159.37 | \$ 159.37 | \$ 71.27 | \$ 71.27 | \$ - | \$ 23.24 | \$ 48.03 |
| 023-003-04300-0000 | \$ 83.88 | \$ - | \$ 37.51 | \$ - | \$ 37.51 | \$ - | \$ 37.51 |
| 023-003-04500-0000 | \$ 100.65 | \$ 100.65 | \$ 45.01 | \$ 45.01 | \$ - | \$ 14.67 | \$ 30.34 |
| 023-003-04510-0000 | \$ 1.93 | \$ - | \$ 0.86 | \$ - | \$ 0.86 | \$ - | \$ 0.86 |
| 023-003-04600-0000 | \$ 25.16 | \$ 25.16 | \$ 11.25 | \$ 11.25 | \$ - | \$ 3.67 | \$ 7.58 |
| 023-003-04700-0000 | \$ 8.39 | \$ - | \$ 3.75 | \$ - | \$ 3.75 | \$ - | \$ 3.75 |
| 023-003-04800-0000 | \$ 527.12 | \$ 527.12 | \$ 235.71 | \$ 235.71 | \$ - | \$ 76.85 | \$ 158.86 |
| 023-003-04900-0000 | \$ 301.31 | \$ 301.31 | \$ 134.74 | \$ 134.74 | \$ - | \$ 43.93 | \$ 90.81 |
| 023-003-05300-0000 | \$ 274.53 | \$ 274.53 | \$ 122.76 | \$ 122.76 | \$ - | \$ 40.02 | \$ 82.74 |
| 023-003-07000-0000 | \$ 1,304.18 | \$ 1,304.18 | \$ 583.19 | \$ 583.19 | \$ - | \$ 190.14 | \$ 393.05 |
| 023-003-10500-0000 | \$ 490.96 | \$ 490.96 | \$ 219.54 | \$ 219.54 | \$ - | \$ 71.58 | \$ 147.96 |
| 023-003-11300-0000 | \$ 450.69 | \$ 450.69 | \$ 201.53 | \$ 201.53 | \$ - | \$ 65.70 | \$ 135.83 |
| 023-003-11600-0000 | \$ 624.92 | \$ - | \$ 279.44 | \$ - | \$ 279.44 | \$ - | \$ 279.44 |
| 023-003-12400-0000 | \$ 569.82 | \$ 569.82 | \$ 254.81 | \$ 254.81 | \$ - | \$ 83.08 | \$ 171.73 |
| 023-003-13300-0000 | \$ 322.89 | \$ - | \$ 144.39 | \$ - | \$ 144.39 | \$ - | \$ 144.39 |
| 023-003-14000-0000 | \$ 244.20 | \$ - | \$ 109.20 | \$ - | \$ 109.20 | \$ - | \$ 109.20 |
| 023-003-14400-0000 | \$ 556.96 | \$ 556.96 | \$ 249.06 | \$ 249.06 | \$ - | \$ 81.20 | \$ 167.86 |
| 023-003-15600-0000 | \$ 72.74 | \$ 72.74 | \$ 32.53 | \$ 32.53 | \$ - | \$ 10.61 | \$ 21.92 |
| 023-003-15700-0000 | \$ 0.95 | \$ - | \$ 0.42 | \$ - | \$ 0.42 | \$ - | \$ 0.42 |

| | | | | | | | |
|--------------------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|
| 023-003-15800-0000 | \$ 0.34 | \$ - | \$ 0.15 | \$ - | \$ 0.15 | \$ - | \$ 0.15 |
| 023-003-15900-0000 | \$ 2.91 | \$ - | \$ 1.30 | \$ - | \$ 1.30 | \$ - | \$ 1.30 |
| 023-003-16200-0000 | \$ 727.96 | \$ - | \$ 325.52 | \$ - | \$ 325.52 | \$ - | \$ 325.52 |
| 023-003-16802-0000 | \$ 116.78 | \$ 116.78 | \$ 52.22 | \$ 52.22 | \$ - | \$ 17.03 | \$ 35.19 |
| 023-006-07600-0000 | \$ 142.27 | \$ 142.27 | \$ 63.62 | \$ 63.62 | \$ - | \$ 20.74 | \$ 42.88 |
| 025-002-00800-0000 | \$ 111.84 | \$ 111.84 | \$ 50.01 | \$ 50.01 | \$ - | \$ 16.30 | \$ 33.71 |
| 025-002-00900-0000 | \$ 226.33 | \$ 226.33 | \$ 101.21 | \$ 101.21 | \$ - | \$ 33.00 | \$ 68.21 |
| 025-002-01000-0000 | \$ 243.25 | \$ 243.25 | \$ 108.77 | \$ 108.77 | \$ - | \$ 35.46 | \$ 73.31 |
| 025-002-01100-0000 | \$ 3.08 | \$ - | \$ 1.38 | \$ - | \$ 1.38 | \$ - | \$ 1.38 |
| 025-002-01200-0000 | \$ 3.22 | \$ - | \$ 1.44 | \$ - | \$ 1.44 | \$ - | \$ 1.44 |
| 025-002-01300-0000 | \$ 2.80 | \$ - | \$ 1.25 | \$ - | \$ 1.25 | \$ - | \$ 1.25 |
| 025-002-03000-0000 | \$ 1.57 | \$ - | \$ 0.70 | \$ - | \$ 0.70 | \$ - | \$ 0.70 |
| 025-002-03400-0000 | \$ 1.57 | \$ - | \$ 0.70 | \$ - | \$ 0.70 | \$ - | \$ 0.70 |
| 025-002-04000-0000 | \$ 4.03 | \$ - | \$ 1.80 | \$ - | \$ 1.80 | \$ - | \$ 1.80 |
| 025-002-04100-0000 | \$ 1.57 | \$ - | \$ 0.70 | \$ - | \$ 0.70 | \$ - | \$ 0.70 |
| 025-002-04700-0000 | \$ 3.13 | \$ - | \$ 1.40 | \$ - | \$ 1.40 | \$ - | \$ 1.40 |
| 025-002-04800-0000 | \$ 6.26 | \$ - | \$ 2.80 | \$ - | \$ 2.80 | \$ - | \$ 2.80 |
| 025-002-05000-0000 | \$ 6.26 | \$ - | \$ 2.80 | \$ - | \$ 2.80 | \$ - | \$ 2.80 |
| 025-002-05200-0000 | \$ 6.26 | \$ - | \$ 2.80 | \$ - | \$ 2.80 | \$ - | \$ 2.80 |
| 025-002-05400-0000 | \$ 1.57 | \$ - | \$ 0.70 | \$ - | \$ 0.70 | \$ - | \$ 0.70 |
| 025-002-05600-0000 | \$ 1.57 | \$ - | \$ 0.70 | \$ - | \$ 0.70 | \$ - | \$ 0.70 |
| 025-002-05700-0000 | \$ 3.13 | \$ - | \$ 1.40 | \$ - | \$ 1.40 | \$ - | \$ 1.40 |
| 025-002-06000-0000 | \$ 1.57 | \$ - | \$ 0.70 | \$ - | \$ 0.70 | \$ - | \$ 0.70 |
| 025-002-06100-0000 | \$ 1.57 | \$ - | \$ 0.70 | \$ - | \$ 0.70 | \$ - | \$ 0.70 |
| 025-002-06200-0000 | \$ 1.57 | \$ - | \$ 0.70 | \$ - | \$ 0.70 | \$ - | \$ 0.70 |
| 025-002-06500-0000 | \$ 1.79 | \$ - | \$ 0.80 | \$ - | \$ 0.80 | \$ - | \$ 0.80 |
| 025-002-06610-0000 | \$ 3.12 | \$ - | \$ 1.40 | \$ - | \$ 1.40 | \$ - | \$ 1.40 |
| 025-002-06612-0000 | \$ 2.37 | \$ - | \$ 1.06 | \$ - | \$ 1.06 | \$ - | \$ 1.06 |
| 025-002-06613-0000 | \$ 3.01 | \$ - | \$ 1.35 | \$ - | \$ 1.35 | \$ - | \$ 1.35 |
| 025-002-06700-0000 | \$ 3.13 | \$ - | \$ 1.40 | \$ - | \$ 1.40 | \$ - | \$ 1.40 |
| 025-002-06710-0000 | \$ 4.25 | \$ - | \$ 1.90 | \$ - | \$ 1.90 | \$ - | \$ 1.90 |
| 025-002-06800-0000 | \$ 596.79 | \$ 596.79 | \$ 266.87 | \$ 266.87 | \$ - | \$ 87.01 | \$ 179.86 |
| 025-002-06900-0000 | \$ 1.57 | \$ - | \$ 0.70 | \$ - | \$ 0.70 | \$ - | \$ 0.70 |
| 025-002-07000-0000 | \$ 1.57 | \$ - | \$ 0.70 | \$ - | \$ 0.70 | \$ - | \$ 0.70 |
| 025-002-07100-0000 | \$ 3.13 | \$ - | \$ 1.40 | \$ - | \$ 1.40 | \$ - | \$ 1.40 |
| 025-002-07300-0000 | \$ 1.57 | \$ - | \$ 0.70 | \$ - | \$ 0.70 | \$ - | \$ 0.70 |
| 025-002-07400-0000 | \$ 1.57 | \$ - | \$ 0.70 | \$ - | \$ 0.70 | \$ - | \$ 0.70 |
| 025-002-07500-0000 | \$ 1.57 | \$ - | \$ 0.70 | \$ - | \$ 0.70 | \$ - | \$ 0.70 |
| 025-002-07600-0000 | \$ 1.57 | \$ - | \$ 0.70 | \$ - | \$ 0.70 | \$ - | \$ 0.70 |
| 025-002-07700-0000 | \$ 2.46 | \$ - | \$ 1.10 | \$ - | \$ 1.10 | \$ - | \$ 1.10 |
| 025-002-07800-0000 | \$ 1.57 | \$ - | \$ 0.70 | \$ - | \$ 0.70 | \$ - | \$ 0.70 |
| 025-002-07900-0000 | \$ 1.57 | \$ - | \$ 0.70 | \$ - | \$ 0.70 | \$ - | \$ 0.70 |
| 025-002-08000-0000 | \$ 1.57 | \$ - | \$ 0.70 | \$ - | \$ 0.70 | \$ - | \$ 0.70 |
| 025-002-08100-0000 | \$ 1.57 | \$ - | \$ 0.70 | \$ - | \$ 0.70 | \$ - | \$ 0.70 |
| 025-002-08200-0000 | \$ 1.57 | \$ - | \$ 0.70 | \$ - | \$ 0.70 | \$ - | \$ 0.70 |
| 025-002-08300-0000 | \$ 1.57 | \$ - | \$ 0.70 | \$ - | \$ 0.70 | \$ - | \$ 0.70 |
| 025-002-08400-0000 | \$ 1.57 | \$ - | \$ 0.70 | \$ - | \$ 0.70 | \$ - | \$ 0.70 |
| 025-002-08500-0000 | \$ 1.57 | \$ - | \$ 0.70 | \$ - | \$ 0.70 | \$ - | \$ 0.70 |
| 025-002-08600-0000 | \$ 1.57 | \$ - | \$ 0.70 | \$ - | \$ 0.70 | \$ - | \$ 0.70 |
| 025-002-08700-0000 | \$ 2.46 | \$ - | \$ 1.10 | \$ - | \$ 1.10 | \$ - | \$ 1.10 |
| 025-002-08900-0000 | \$ 2.46 | \$ - | \$ 1.10 | \$ - | \$ 1.10 | \$ - | \$ 1.10 |
| 025-002-09000-0000 | \$ 273.33 | \$ - | \$ 122.22 | \$ - | \$ 122.22 | \$ - | \$ 122.22 |
| 025-002-09100-0000 | \$ 1.57 | \$ - | \$ 0.70 | \$ - | \$ 0.70 | \$ - | \$ 0.70 |
| 025-002-09300-0000 | \$ 4.70 | \$ - | \$ 2.10 | \$ - | \$ 2.10 | \$ - | \$ 2.10 |
| 025-002-09400-0000 | \$ 2.68 | \$ - | \$ 1.20 | \$ - | \$ 1.20 | \$ - | \$ 1.20 |
| 025-002-09500-0000 | \$ 3.58 | \$ - | \$ 1.60 | \$ - | \$ 1.60 | \$ - | \$ 1.60 |
| 025-002-09600-0000 | \$ 4.47 | \$ - | \$ 2.00 | \$ - | \$ 2.00 | \$ - | \$ 2.00 |
| 025-002-09700-0000 | \$ 3.58 | \$ - | \$ 1.60 | \$ - | \$ 1.60 | \$ - | \$ 1.60 |
| 025-002-09800-0000 | \$ 1.12 | \$ - | \$ 0.50 | \$ - | \$ 0.50 | \$ - | \$ 0.50 |
| 025-002-09900-0000 | \$ 2.91 | \$ - | \$ 1.30 | \$ - | \$ 1.30 | \$ - | \$ 1.30 |
| 025-002-10000-0000 | \$ 1.79 | \$ - | \$ 0.80 | \$ - | \$ 0.80 | \$ - | \$ 0.80 |
| 025-002-10100-0000 | \$ 1.79 | \$ - | \$ 0.80 | \$ - | \$ 0.80 | \$ - | \$ 0.80 |
| 025-002-10200-0000 | \$ 2.24 | \$ - | \$ 1.00 | \$ - | \$ 1.00 | \$ - | \$ 1.00 |
| 025-002-10300-0000 | \$ 2.91 | \$ - | \$ 1.30 | \$ - | \$ 1.30 | \$ - | \$ 1.30 |
| 025-002-10400-0000 | \$ 1.79 | \$ - | \$ 0.80 | \$ - | \$ 0.80 | \$ - | \$ 0.80 |
| 025-002-10410-0000 | \$ 3.80 | \$ - | \$ 1.70 | \$ - | \$ 1.70 | \$ - | \$ 1.70 |
| 025-002-10500-0000 | \$ 4.25 | \$ - | \$ 1.90 | \$ - | \$ 1.90 | \$ - | \$ 1.90 |
| 025-002-10600-0000 | \$ 840.87 | \$ 840.87 | \$ 376.01 | \$ 376.01 | \$ - | \$ 122.59 | \$ 253.42 |
| 025-002-10750-0000 | \$ 1.57 | \$ - | \$ 0.70 | \$ - | \$ 0.70 | \$ - | \$ 0.70 |
| 025-002-10800-0000 | \$ 2.68 | \$ - | \$ 1.20 | \$ - | \$ 1.20 | \$ - | \$ 1.20 |
| 025-002-10900-0000 | \$ 3.36 | \$ - | \$ 1.50 | \$ - | \$ 1.50 | \$ - | \$ 1.50 |
| 025-002-11000-0000 | \$ 8.50 | \$ - | \$ 3.80 | \$ - | \$ 3.80 | \$ - | \$ 3.80 |
| 025-002-11100-0000 | \$ 1.79 | \$ - | \$ 0.80 | \$ - | \$ 0.80 | \$ - | \$ 0.80 |

| | | | | | | | |
|------------------------|---------------------|---------------------|---------------------|--------------------|-----------------------------|--------------------|--------------------|
| 025-002-11105-0000 | \$ 3.36 | \$ - | \$ 1.50 | \$ - | \$ 1.50 | \$ - | \$ 1.50 |
| 025-002-11120-0000 | \$ 3.36 | \$ - | \$ 1.50 | \$ - | \$ 1.50 | \$ - | \$ 1.50 |
| 025-002-11200-0000 | \$ 3.63 | \$ - | \$ 1.62 | \$ - | \$ 1.62 | \$ - | \$ 1.62 |
| 025-002-11300-0000 | \$ 352.01 | \$ - | \$ 157.41 | \$ - | \$ 157.41 | \$ - | \$ 157.41 |
| 025-002-11400-0000 | \$ 1.57 | \$ - | \$ 0.70 | \$ - | \$ 0.70 | \$ - | \$ 0.70 |
| 025-002-11500-0000 | \$ 1.57 | \$ - | \$ 0.70 | \$ - | \$ 0.70 | \$ - | \$ 0.70 |
| 025-002-11600-0000 | \$ 1.57 | \$ - | \$ 0.70 | \$ - | \$ 0.70 | \$ - | \$ 0.70 |
| 025-002-11700-0000 | \$ 2.01 | \$ - | \$ 0.90 | \$ - | \$ 0.90 | \$ - | \$ 0.90 |
| 025-002-11800-0000 | \$ 3.13 | \$ - | \$ 1.40 | \$ - | \$ 1.40 | \$ - | \$ 1.40 |
| 025-002-11900-0000 | \$ 1.57 | \$ - | \$ 0.70 | \$ - | \$ 0.70 | \$ - | \$ 0.70 |
| 025-002-12000-0000 | \$ 1.57 | \$ - | \$ 0.70 | \$ - | \$ 0.70 | \$ - | \$ 0.70 |
| 025-002-12400-0000 | \$ 1.57 | \$ - | \$ 0.70 | \$ - | \$ 0.70 | \$ - | \$ 0.70 |
| 025-002-12500-0000 | \$ 3.13 | \$ - | \$ 1.40 | \$ - | \$ 1.40 | \$ - | \$ 1.40 |
| 025-002-12700-0000 | \$ 3.14 | \$ - | \$ 1.40 | \$ - | \$ 1.40 | \$ - | \$ 1.40 |
| 025-002-13100-0000 | \$ 1.57 | \$ - | \$ 0.70 | \$ - | \$ 0.70 | \$ - | \$ 0.70 |
| 025-002-13200-0000 | \$ 1.57 | \$ - | \$ 0.70 | \$ - | \$ 0.70 | \$ - | \$ 0.70 |
| 025-002-13500-0000 | \$ 1.57 | \$ - | \$ 0.70 | \$ - | \$ 0.70 | \$ - | \$ 0.70 |
| 025-002-13600-0000 | \$ 28.24 | \$ 28.24 | \$ 12.63 | \$ 12.63 | \$ - | \$ 4.12 | \$ 8.51 |
| 025-002-13700-0000 | \$ 253.17 | \$ 253.17 | \$ 113.21 | \$ 113.21 | \$ - | \$ 36.91 | \$ 76.30 |
| 025-002-13800-0000 | \$ 715.91 | \$ 715.91 | \$ 320.13 | \$ 320.13 | \$ - | \$ 104.37 | \$ 215.76 |
| 025-002-13850-0000 | \$ 3.90 | \$ - | \$ 1.74 | \$ - | \$ 1.74 | \$ - | \$ 1.74 |
| 025-002-15000-0000 | \$ 5.59 | \$ - | \$ 2.50 | \$ - | \$ 2.50 | \$ - | \$ 2.50 |
| 025-002-15100-0000 | \$ 5.52 | \$ - | \$ 2.47 | \$ - | \$ 2.47 | \$ - | \$ 2.47 |
| 025-002-15120-0000 | \$ 0.07 | \$ - | \$ 0.03 | \$ - | \$ 0.03 | \$ - | \$ 0.03 |
| 025-002-15200-0000 | \$ 41.94 | \$ 41.94 | \$ 18.75 | \$ 18.75 | \$ - | \$ 6.11 | \$ 12.64 |
| 025-002-25000-0000 | \$ 27.96 | \$ 27.96 | \$ 12.50 | \$ 12.50 | \$ - | \$ 4.08 | \$ 8.42 |
| 025-002-25200-0000 | \$ 33.97 | \$ - | \$ 15.19 | \$ - | \$ 15.19 | \$ - | \$ 15.19 |
| 025-002-25300-0000 | \$ 8.53 | \$ - | \$ 3.81 | \$ - | \$ 3.81 | \$ - | \$ 3.81 |
| 025-002-25400-0000 | \$ 518.92 | \$ 518.92 | \$ 232.04 | \$ 232.04 | \$ - | \$ 75.65 | \$ 156.39 |
| 025-002-25480-0000 | \$ 162.72 | \$ - | \$ 72.76 | \$ - | \$ 72.76 | \$ - | \$ 72.76 |
| 025-002-25600-0000 | \$ 422.04 | \$ 422.04 | \$ 188.72 | \$ 188.72 | \$ - | \$ 61.53 | \$ 127.19 |
| 025-002-25700-0000 | \$ 280.15 | \$ 280.15 | \$ 125.27 | \$ 125.27 | \$ - | \$ 40.84 | \$ 84.43 |
| 025-002-25710-0000 | \$ 2.66 | \$ - | \$ 1.19 | \$ - | \$ 1.19 | \$ - | \$ 1.19 |
| 025-002-25750-0000 | \$ 280.01 | \$ 280.01 | \$ 125.21 | \$ 125.21 | \$ - | \$ 40.82 | \$ 84.39 |
| 025-002-25800-0000 | \$ 266.73 | \$ 266.73 | \$ 119.27 | \$ 119.27 | \$ - | \$ 38.89 | \$ 80.38 |
| 025-002-25900-0000 | \$ 4.19 | \$ - | \$ 1.87 | \$ - | \$ 1.87 | \$ - | \$ 1.87 |
| 025-002-25950-0000 | \$ 8.39 | \$ - | \$ 3.75 | \$ - | \$ 3.75 | \$ - | \$ 3.75 |
| 025-002-26000-0000 | \$ 236.39 | \$ 236.39 | \$ 105.71 | \$ 105.71 | \$ - | \$ 34.46 | \$ 71.25 |
| 025-002-26200-0000 | \$ 5.59 | \$ - | \$ 2.50 | \$ - | \$ 2.50 | \$ - | \$ 2.50 |
| 025-002-28100-0000 | \$ 55.92 | \$ 55.92 | \$ 25.01 | \$ 25.01 | \$ - | \$ 8.15 | \$ 16.86 |
| 025-002-28200-0000 | \$ 282.81 | \$ 282.81 | \$ 126.46 | \$ 126.46 | \$ - | \$ 41.23 | \$ 85.23 |
| 025-002-28250-0000 | \$ 42.22 | \$ - | \$ 18.88 | \$ - | \$ 18.88 | \$ - | \$ 18.88 |
| 025-002-28300-0000 | \$ 2.80 | \$ - | \$ 1.25 | \$ - | \$ 1.25 | \$ - | \$ 1.25 |
| 025-002-28800-0000 | \$ 75.94 | \$ 75.94 | \$ 33.96 | \$ 33.96 | \$ - | \$ 11.07 | \$ 22.89 |
| 025-002-28802-0000 | \$ 2.35 | \$ - | \$ 1.05 | \$ - | \$ 1.05 | \$ - | \$ 1.05 |
| 025-002-28900-0000 | \$ 746.04 | \$ 746.04 | \$ 333.61 | \$ 333.61 | \$ - | \$ 108.74 | \$ 224.87 |
| 025-002-29000-0000 | \$ 535.77 | \$ 535.77 | \$ 239.58 | \$ 239.58 | \$ - | \$ 78.11 | \$ 161.47 |
| 025-002-29005-0000 | \$ 8.00 | \$ - | \$ 3.58 | \$ - | \$ 3.58 | \$ - | \$ 3.58 |
| 025-002-29010-0000 | \$ 37.29 | \$ - | \$ 16.67 | \$ - | \$ 16.67 | \$ - | \$ 16.67 |
| 025-002-29020-0000 | \$ 112.28 | \$ 112.28 | \$ 50.21 | \$ 50.21 | \$ - | \$ 16.37 | \$ 33.84 |
| 025-002-29050-0000 | \$ 31.65 | \$ - | \$ 14.15 | \$ - | \$ 14.15 | \$ - | \$ 14.15 |
| CN Rail | \$ 89.47 | \$ - | \$ 40.01 | \$ - | \$ 40.01 | \$ - | \$ 40.01 |
| Haldimand County Roads | \$ 1,758.38 | \$ - | \$ 786.42 | \$ - | \$ 786.42 | \$ - | \$ 786.42 |
| | \$ 23,000.86 | \$ 17,332.03 | \$ 10,285.27 | \$ 7,750.35 | \$ 2,534.92 | \$ 2,526.83 | \$ 7,758.44 |
| | | | | | Haldimand County | \$ 786.42 | |
| | | | | | Amounts to be Billed | \$ 6,972.02 | |

Project Name: North Hutchinson North Maintenance

| | | | | | |
|---------------------------|--------------------------------|--------------------------------|--------------------------------------|--|-----------------------|
| Final Project Cost | Additional County Costs | Total Report Assessment | Total Agricultural Assessment | Pro Rated Agricultural Assessment | Grant Received |
| \$13,882.56 | | \$1,945.00 | \$1,088.00 | \$7,765.68 | \$4,627.52 |

| Roll Number | Total Assessment | Agricultural Lands Assessed (\$) | Gross Costs (\$) | Agricultural Lands Assessed (\$) | Non Agricultural Lands Assessed (\$) | Grant Received (\$) | Net Assessment (\$) |
|--------------------|--------------------|----------------------------------|---------------------|----------------------------------|--------------------------------------|---------------------|---------------------|
| 023-002-26700-0000 | \$ 125.00 | \$ 125.00 | \$ 892.20 | \$ 892.20 | \$ - | \$ 531.66 | \$ 360.54 |
| 023-002-26800-0000 | \$ 37.00 | \$ - | \$ 264.09 | \$ - | \$ 264.09 | \$ - | \$ 264.09 |
| 023-002-26900-0000 | \$ 25.00 | \$ - | \$ 178.44 | \$ - | \$ 178.44 | \$ - | \$ 178.44 |
| 023-004-06300-0000 | \$ 5.00 | \$ 5.00 | \$ 35.69 | \$ 35.69 | \$ - | \$ 21.27 | \$ 14.42 |
| 023-004-06500-0000 | \$ 8.00 | \$ 8.00 | \$ 57.10 | \$ 57.10 | \$ - | \$ 34.03 | \$ 23.07 |
| 023-004-06600-0000 | \$ 84.00 | \$ 84.00 | \$ 599.56 | \$ 599.56 | \$ - | \$ 357.27 | \$ 242.29 |
| 023-004-07150-0000 | \$ 55.00 | \$ 55.00 | \$ 392.57 | \$ 392.57 | \$ - | \$ 233.93 | \$ 158.64 |
| 023-004-09100-0000 | \$ 291.00 | \$ 291.00 | \$ 2,077.03 | \$ 2,077.03 | \$ - | \$ 1,237.69 | \$ 839.34 |
| 023-004-09500-0000 | \$ 2.00 | \$ - | \$ 14.28 | \$ - | \$ 14.28 | \$ - | \$ 14.28 |
| 023-004-09600-0000 | \$ 240.00 | \$ - | \$ 1,713.02 | \$ - | \$ 1,713.02 | \$ - | \$ 1,713.02 |
| 023-004-09700-0000 | \$ 52.00 | \$ - | \$ 371.15 | \$ - | \$ 371.15 | \$ - | \$ 371.15 |
| 023-004-09800-0000 | \$ 52.00 | \$ - | \$ 371.15 | \$ - | \$ 371.15 | \$ - | \$ 371.15 |
| 023-004-09900-0000 | \$ 370.00 | \$ 370.00 | \$ 2,640.90 | \$ 2,640.90 | \$ - | \$ 1,573.70 | \$ 1,067.20 |
| 023-004-12000-0000 | \$ 150.00 | \$ 150.00 | \$ 1,070.63 | \$ 1,070.63 | \$ - | \$ 637.97 | \$ 432.66 |
| 023-004-16000-0000 | \$ 10.00 | \$ - | \$ 71.38 | \$ - | \$ 71.38 | \$ - | \$ 71.38 |
| Haldimand County | \$ 439.00 | \$ - | \$ 3,133.37 | \$ - | \$ 3,133.37 | \$ - | \$ 3,133.37 |
| | \$ 1,945.00 | \$ 1,088.00 | \$ 13,882.56 | \$ 7,765.68 | \$ 6,116.88 | \$ 4,627.52 | \$ 9,255.04 |
| | | | | | Haldimand County | | \$ 3,133.37 |
| | | | | | Amounts to be Billed | | \$ 6,121.67 |

Project Name: County Road 3 Drain

| | | | | | |
|---------------------------|--------------------------------|--------------------------------|--------------------------------------|--|-----------------------|
| <u>Final Project Cost</u> | <u>Additional County Costs</u> | <u>Total Report Assessment</u> | <u>Total Agricultural Assessment</u> | <u>Pro Rated Agricultural Assessment</u> | <u>Grant Received</u> |
| \$199.41 | | \$277.00 | \$0.00 | \$0.00 | \$0.00 |

| Roll Number | Total Assessment | Agricultural Lands Assessed (\$) | Gross Costs (\$) | Agricultural Lands Assessed (\$) | Non Agricultural Lands Assessed (\$) | Grant Received (\$) | Net Assessment (\$) |
|-----------------------------|------------------|----------------------------------|------------------|----------------------------------|--------------------------------------|---------------------|---------------------|
| 332-007-21000-0000 | \$ 166.00 | \$ - | \$ 119.50 | \$ - | \$ 119.50 | \$ - | \$ 119.50 |
| 332-007-21100-0000 | \$ 16.00 | \$ - | \$ 11.52 | \$ - | \$ 11.52 | \$ - | \$ 11.52 |
| 332-007-21200-0000 | \$ 95.00 | \$ - | \$ 68.39 | \$ - | \$ 68.39 | \$ - | \$ 68.39 |
| | \$ 277.00 | \$ - | \$ 199.41 | \$ - | \$ 199.41 | \$ - | \$ 199.41 |
| Haldimand County | | | | | | | \$ - |
| Amounts to be Billed | | | | | | | \$ 199.41 |